



RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME MONTESSORI SCHOOL OF CHINO HILLS			REINSPECTION DATE Not Specified	INSPECTOR Yanan Zhu	DATE 7/12/2016
LOCATION 14635 PIPELINE AV, CHINO, CA 91710			PERMIT EXPIRATION 7/31/2016	IDENTIFIER: Pool SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION RESULT: 05 - CORRECTIVE ACTION / FOLLOW UP REQU ACTION: 03 - REINSPECTION REQUIRED	
TIME IN 5:02 PM	TIME OUT 5:30 PM	FACILITY ID FA0004795	RELATED ID PR0015229	PE 3620	


RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	24
volume (gal)	8,796
area (sq ft)	382
occupancy	14

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K994 Reinspection

POINTS
NA

Compliance Date: Not Specified
Not In Compliance
Violation Reference - HSC

Inspector Comments: Re-inspection was conducted today to determine the compliance from prior inspection regarding the gate violation. The gate was self-closing, but not self-latching at the time of last inspection. Operator stated that she had informed the owner about the issue, but the gate has not been fixed yet. A billable re-reinspection will be conducted within this week regarding gate violation compliance, at an hourly rate of \$245/hour with 30 minutes minimum.

Gate was checked again, it was self-closing, but still not self-latching at the time of reinspection.

Description: Reinspection conducted at this time to determine compliance from prior inspection.

Overall Inspection Comments

No summary comments have been made for this inspection.

Signature(s) of Acknowledgement

NAME: Maria Castro
TITLE: Coordinator

Total # of Images: 0