



**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

www.sbcounty.gov/dehs

(800) 442-2283

FACILITY NAME LA FITNESS				DATE 6/6/2013	SIGNATURE	
LOCATION 9385 MONTE VISTA RD, MONTCLAIR, CA 91763				REINSPECTION DATE 12/06/2013	PERMIT EXPIRATION 11/30/2013	
MAILING ADDRESS PO BOX 52110, IRVINE CA 92619				REHS Jose Rodriguez		
<input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input checked="" type="checkbox"/> ACCOUNT				PROGRAM IDENTIFIER: Spa		
FA # FA0008507	PR # PR0014482	SR # Not Specified	CO # Not Specified	PE 3601	SERVICE: 001 - Inspection - Routine	
TIME IN 10:59 AM	TIME OUT 11:10 AM	CONTACT Not Captured			RESULT: 03 - Corrective Action / No Follow up Required	
				ACTION: 01 - No Further Action Required		

RECREATIONAL HEALTH - PUBLIC POOL/SPA



Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

100

SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	240
volume (gal)	7,200
area (sq ft)	240
occupancy	24

36K952 Drained Pool or Spa Inspection

POINTS NA	Compliance Date: Not Specified	Inspector Comments: Spa is drained. Facility is undergoing renovations and is closed to the public at this time. Spa was drained because of the excess dust accumulation in the facility.
	Not In Compliance	
	Violation Reference - HSC	

Violation Description: An inspection was conducted at this time on a drained pool or spa. Contact DEHS prior to filling with water and/or operating.

Overall Inspection Comments

No summary comments have been made for this inspection.

Photo Attachments:

No Photo Attachments