



Public Health
Environmental Health Services




www.SBCounty.gov

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME RADISSON ONTARIO AIRPORT		DATE 5/28/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 8/31/2014
LOCATION 2200 E HOLT BL, ONTARIO, CA 91761			INSPECTOR John Ramos	
MAILING ADDRESS 2155 E CONVENTION CENTER WY, ONTARIO CA 91764			IDENTIFIER: Spa	
<input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input checked="" type="checkbox"/> ACCOUNT			SERVICE: 037 - POOL/SPA - BILLABLE INSPECTION SERVIC	
TIME IN 10:12 AM	TIME OUT 10:48 AM	FACILITY ID FA0006518	RELATED ID PR0013910	PE 3623
RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED				
ACTION: 15 - PERMIT REINSTATED / FACILITY RE-OPEN				

RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K992 Permit Reinstatement

POINTS NA	Compliance Date: Not Specified	Inspector Comments: Permit is hereby reinstated. A reinspection was conducted to determine compliance with a previously observed violation. Spa is reopened.
	Complied on 5/28/2015	
	Violation Reference - HSC	

Description: The health permit to operate is hereby reinstated and facility may open.

36K993 Re-Reinspection

POINTS NA	Compliance Date: Not Specified	Inspector Comments: A reinspection was conducted to determine compliance with a previously observed violation. Observed GFCI repaired. Spa reopened.
	Complied on 5/28/2015	
	Violation Reference - HSC	

Description: Billable re-inspection conducted at the time to determine compliance from prior inspection.

Overall Inspection Comments

Permit is hereby reinstated. A reinspection was conducted to determine compliance with a previously observed violation. Spa is reopened.

Observed GFCI repaired.
Spa reopened.

Signature(s) of Acknowledgement

NAME:
TITLE:

Total # of Images: 0