



**Public Health**  
Environmental Health Services




www.SBCounty.gov

**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME MADISON PARK ALTA LOMA		DATE 6/16/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 7/31/2015
LOCATION 10757 LEMON AV, RANCHO CUCAMONGA, CA 91701			INSPECTOR Dior Porter	
MAILING ADDRESS 800 IRON POINT RD, FOLSOM CA 95630			IDENTIFIER: Wading Pool	
			SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION	
TIME IN 12:18 PM	TIME OUT 12:33 PM	FACILITY ID FA0004884	RELATED ID PR0015433	PE 3621
			RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED	
			ACTION: 15 - PERMIT REINSTATED / FACILITY RE-OPEN	

**RECREATIONAL HEALTH - Public Pool - Additional Pool at Facility**

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

**IMPORTANT: Replacement of Suction Outlet Covers**  
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

**36K992 Permit Reinstatement**

POINTS <b>NA</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b> Observed recirculation system in operation. Observed flow of 60gpm. Permit reinstated.
	Not In Compliance	
	Violation Reference - HSC	

**Description:** The health permit to operate is hereby reinstated and facility may open.

**36K994 Reinspection**

POINTS <b>NA</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b> Reinspection to determine compliance for recirculation system. Observed recirculation system in operation. Observed flow of 60gpm.
	Not In Compliance	
	Violation Reference - HSC	

**Description:** Reinspection conducted at this time to determine compliance from prior inspection.

**Overall Inspection Comments**

No summary comments have been made for this inspection.

**Signature(s) of Acknowledgement**

NAME:  
TITLE:  
Total # of Images: 0