



Public Health
Environmental Health Services



www.SBCounty.gov

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME RIVERA APARTMENT HOMES		DATE 6/17/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 6/30/2015
LOCATION 92 KANSAS ST, REDLANDS, CA 92373			INSPECTOR Yvette Velasco	
MAILING ADDRESS 2900 ADAMS ST C200, RIVERSIDE CA 92504			IDENTIFIER: North Spa	
<input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input checked="" type="checkbox"/> ACCOUNT			SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION	
TIME IN 11:43 AM	TIME OUT 12:05 PM	FACILITY ID FA0005930	RELATED ID PR0013709	PE 3623
RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE				
ACTION: 01 - NO FURTHER ACTION REQUIRED				

RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	28
volume (gal)	844
area (sq ft)	63
occupancy	6

IMPORTANT: Replacement of Suction Outlet Covers

Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K994 Reinspection

POINTS
NA

Compliance Date: Not Specified
Not In Compliance
Violation Reference - HSC

Inspector Comments: During the last routine inspection the back flow was observed with no drain.

Observed no drain available for backwashing. Observed blue hose attached to separation tank but PIC was unsure of where the hose led to during backwashing.

Ensure to provide appropriate drain for backwashing. Inspector will follow up during the next routine inspection to ensure that appropriate drain is provided. There is no further action required at this time.

Description: Reinspection conducted at this time to determine compliance from prior inspection.

Overall Inspection Comments

No summary comments have been made for this inspection.

Signature(s) of Acknowledgement

NAME: Mayra Velasco
TITLE:

Total # of Images: 0