





Public Health
Environmental Health Services

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME FAIRWAY PARK CONDO POOL			DATE 7/30/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 6/30/2016
LOCATION 3210 LITTLE MOUNTAIN DR, SAN BERNARDINO, CA 92405				INSPECTOR Yvette Velasco	
MAILING ADDRESS 3210 LITTLE MOUNTAIN DR, SAN BERNARDINO, CA 92405				IDENTIFIER: Spa	
<input checked="" type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input type="checkbox"/> ACCOUNT				SERVICE: 008 - INSPECTION - ATTEMPTED	
TIME IN 10:24 AM	TIME OUT 10:32 AM	FACILITY ID FA0008899	RELATED ID PR0014189	PE 3623	RESULT: 00 - NOT APPLICABLE
					ACTION: 00 - NOT APPLICABLE

RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

IMPORTANT: Replacement of Suction Outlet Covers
 Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K996 Attempted Inspection

POINTS NA	Compliance Date: Not Specified	Inspector Comments: A routine inspection was attempted. Observed pool area locked with no key provided. Observed no manager on site and phone number on file disconnected. Ensure to provide access to the pool area for inspections. Inspector will attempt at a later date.
	Not In Compliance	
	Violation Reference - HSC	

Description: An inspection was attempted today. Another inspection will be attempted at a later date.

Overall Inspection Comments

No summary comments have been made for this inspection.

Signature(s) of Acknowledgement

NAME:
 TITLE:
 Total # of Images: 0