






RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME NORMANDY APARTMENTS			DATE 9/8/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 10/31/2015
LOCATION 4700 N SIERRA WY, SAN BERNARDINO, CA 92404				INSPECTOR Yvette Velasco	
MAILING ADDRESS 4700 N SIERRA WY, SAN BERNARDINO, CA 92404			<input checked="" type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input type="checkbox"/> ACCOUNT IDENTIFIER: Pool SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE ACTION: 15 - PERMIT REINSTATED / FACILITY RE-OPEN		
TIME IN 9:39 AM	TIME OUT 10:25 AM	FACILITY ID FA0008854	RELATED ID PR0013763	PE 3620	

RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K992 Permit Reinstatement

POINTS
NA

Compliance Date: Not Specified
Not In Compliance
Violation Reference - HSC

Inspector Comments: During the last routine inspection the light fixture inside the pool was observed lose, the gate was observed not self latching, free chlorine levels were observed at 0.0ppm, and the separation tank was observed not on the recirculation system.

Observed the light fixture intact, the gate self latching, and free chlorine levels at 9.6ppm. The facility was given 7 days to repair the separation tank, by 9/10/15.

The health inspector will follow up after this date to ensure that the separation tanks is properly installed with the recirculation system.

Description: The health permit to operate is hereby reinstated and facility may open.

Overall Inspection Comments

No summary comments have been made for this inspection.

Signature(s) of Acknowledgement

NAME:
TITLE:

Total # of Images: 0