



Public Health
Environmental Health Services

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME INLAND EMPIRE JOB CORPS		DATE 6/25/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 6/30/2015
LOCATION 3173 KERRY ST, SAN BERNARDINO, CA 92407			INSPECTOR Sumedha Singh	
MAILING ADDRESS 3173 KERRY ST, SAN BERNARDINO CA 92407			IDENTIFIER: Pool	
TIME IN 8:17 AM			SERVICE: 001 - INSPECTION - ROUTINE	
TIME OUT 9:00 AM			RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE	
FACILITY ID FA0005610			ACTION: 01 - NO FURTHER ACTION REQUIRED	
RELATED ID PR0007348			PE 3620	

RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility



Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

93

SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$ 4.08 per 1 minute with a minimum time of 30 minutes, and a minimum charge of \$122.50.

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	140
volume (gal)	67,500
area (sq ft)	1,800
occupancy	90

IMPORTANT: Replacement of Suction Outlet Covers

Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K570 Maintenance – Critical – Flow rate/Turnover rate ⚠ CRITICAL ⚠

POINTS 5	Compliance Date: Not Specified	Inspector Comments: Observed flow meter in equipment room reading approximately 60 gpm. Flow meter should be functioning at a minimum of 140 gpm for a turnover rate of 8 hours due to being built prior to 1982.
	Not In Compliance	
	Violation Reference - CCR - 3124B, 65525	

Violation Description: The recirculation system shall have the capacity to provide a complete turnover of pool water in:

1. One-half hour or less for a spa pool; and
2. One-half hour or less for a spray ground; and
3. One hour or less for a wading pool; and
4. Two hours or less for a medical pool; and
5. Six hours or less for all other types of public pools.

The variation in flow rate of an operating recirculation system shall be such as not to reduce the flow below 75 percent of the rate required in section 3124B, Title 24, California Code of Regulations.

36K558 Equipment – Water supply

POINTS 1	Compliance Date: Not Specified	Inspector Comments: Observed closed loop system in equipment room. Backwash water is plumbed back into pool return line. Closed loop systems are not allowed. Wastewater shall be disposed of properly.
	Not In Compliance	
	Violation Reference - CCR - 3127B	

Violation Description: There shall be no direct connection between any potable water supply system and the pool or its piping system unless protected by a backflow prevention device in accordance with Chapter 6 of the California Plumbing Code.



Public Health
Environmental Health Services

www.SBCounty.gov

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME INLAND EMPIRE JOB CORPS	DATE 6/25/2015
LOCATION 3173 KERRY ST, SAN BERNARDINO, CA 92407	INSPECTOR Sumedha Singh

IMPORTANT: Replacement of Suction Outlet Covers

Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K597 Construction - Pool shell tiles and surface

POINTS 1	Compliance Date: Not Specified Not In Compliance Violation Reference - CCR - 3108B	Inspector Comments: Observed broken tiles near the shallow and deep end of the pool. Repair and maintain as needed.
		Observed large facility logo at the bottom of the pool. No marking, designs or lettering is permitted on the pool shell. Logo shall be removed.

Violation Description: The finished pool shell shall be lined with a smooth waterproof interior finish that will withstand repeated brushing, scrubbing and cleaning procedures. The interior pool finish shall completely line the pool to the tile lines, coping, or cantilevered deck.

The finish color shall be white except for the following which shall be of contrasting color:

1. Lane and other required pool markings described in Section 3110B of the California Code of Regulations; and
2. The top surface edges of benches in spa pools; and
3. The edge of pool steps; and
4. Tiles installed at the waterline; and
5. Tiles installed at the 4 1/2-foot (1372 mm) depth line.

Overall Inspection Comments

No summary comments have been made for this inspection.

Signature(s) of Acknowledgement

NAME: Kevin Gebo
TITLE: Safety and Security Manager

Total # of Images: 0