



RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME SAN GORGONIO HIGH SCHOOL		DATE 9/10/2015	REINSPECTION DATE 9/24/2015	PERMIT EXPIRATION
LOCATION 2299 E PACIFIC ST, SAN BERNARDINO, CA 92404			INSPECTOR Sierra Clayborn	
MAILING ADDRESS 2299 E PACIFIC ST, SAN BERNARDINO, CA 92404		<input checked="" type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input type="checkbox"/> ACCOUNT IDENTIFIER: Shallow Pool SERVICE: 001 - INSPECTION - ROUTINE RESULT: 05 - CORRECTIVE ACTION / FOLLOW UP REQU ACTION: 03 - REINSPECTION REQUIRED		
TIME IN 1:50 PM	TIME OUT 2:24 PM	FACILITY ID FA0006488	RELATED ID PR0014844	PE 3603

RECREATIONAL HEALTH - Public School Pool / Spa

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$4.08 per 1 minute with a minimum time of 30 minutes, and a minimum charge of \$122.50.




98

SCORE

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	375
required flow (gpm)	274
volume (gal)	131,600
area (sq ft)	4,680
occupancy	234

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K548 Equipment - General Requirements - System Description

POINTS 1	Compliance Date: Not Specified	Inspector Comments: Observed 17 outlet vent covers missing from bottom of shallow pool, which poses a tripping hazard. Replace as soon as possible.
	Not In Compliance	
	Violation Reference - CCR 24 - 3123B.1	

Violation Description: Each pool shall be provided with a separate recirculation system designed for the continuous recirculation, filtration and disinfection of the pool water. The system shall consist of pumps, filters, chemical feeders, skimmers or perimeter overflow systems, valves, pipes, connections, fittings and appurtenances.

36K566 Lighting – Requirements

POINTS 1	Compliance Date: Not Specified	Inspector Comments: Observed 1 light out in shallow pool. GFCI functioning properly. Investigate. Ensure that underwater lights are functioning properly.
	Not In Compliance	
	Violation Reference - CCR - 3115B	

Violation Description: Pools shall have underwater and deck lighting such that lifeguards or other persons may observe, without interference from direct and reflected glare from the lighting sources, every part of the underwater area and pool surface, all diving boards or other pool appurtenances.

Overall Inspection Comments

No summary comments have been made for this inspection.

Signature(s) of Acknowledgement



Public Health
Environmental Health Services

www.SBCounty.gov
www.SBCounty.gov/dph/dehs

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

<small>FACILITY NAME</small> SAN GORGONIO HIGH SCHOOL	<small>DATE</small> 9/10/2015
<small>LOCATION</small> 2299 E PACIFIC ST, SAN BERNARDINO, CA 92404	<small>INSPECTOR</small> Sierra Clayborn

NAME: Charles Thomas Zylman
TITLE: Lead Pool Attendant

Total # of Images: 0