



**County of San Bernardino • Department of Public Health**  
**Division of Environmental Health Services**  
**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM**  
**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

[www.sbcounty.gov/dehs](http://www.sbcounty.gov/dehs)

**(800) 442-2283**

FACILITY NAME <b>FRIENDLY HILLS M EST LLC</b>					DATE <b>9/28/2012</b>	SIGNATURE	
LOCATION <b>2140 S MENTONE BL, MENTONE, CA 92359</b>					REINSPECTION DATE <b>3/28/2013</b>	PERMIT EXPIRATION <b>12/31/2012</b>	
MAILING ADDRESS <b>250 W FIRST ST 205, CLAREMONT CA 91711-4743</b>					<input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input checked="" type="checkbox"/> ACCOUNT REHS <b>Yong Aday</b>		
FA # <b>FA0007184</b>	PR # <b>PR0014712</b>	SR # <b>Not Specified</b>	CO # <b>Not Specified</b>	PE <b>3601</b>	PROGRAM IDENTIFIER: <b>pool</b>		
TIME IN <b>3:21 PM</b>	TIME OUT <b>3:40 PM</b>	CONTACT <b>Not Captured</b>			SERVICE: 001 - Inspection - Routine		
					RESULT: 03 - Corrective Action / No Follow up Required		
					ACTION: 01 - No Further Action Required		




**RECREATIONAL HEALTH - PUBLIC POOL/SPA**

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50

**Recreational Health Details**

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	120
required flow (gpm)	150
volume (gal)	72,000
area (sq ft)	0
occupancy	45

**Inspection Violations**

**Non-critical Violations**

**1. Skimmers - Float Assembly- Air Lock Device**

Compliance Date not Specified  
 Not In Compliance  
 Violation Reference: CCR 24 - 3134B.1

*Violation Description:* The skimmer shall be provided with an air-lock protective device that shall not permit leakage of air into the recirculation suction piping system. This device shall not leak more than 3 gpm of water during normal operation.

*Inspector Comments:* Observed wrong type of float assemblies in skimmers. Replace them with the ball-shape type.

**2. Skimmers - Weir**

Compliance Date not Specified  
 Not In Compliance  
 Violation Reference: CCR 24 - 3134

*Violation Description:* Skimmer(s) shall have a weir which automatically adjusts to variations of the water level less than 4 inches.

*Inspector Comments:* Replace missing weir gate for one skimmer.

**3. Water Quality - Cyanurates**

Compliance Date not Specified  
 Not In Compliance  
 Violation Reference: CCR - 65529(a)

*Violation Description:* The cyanuric acid concentration in any pool shall not exceed 100 ppm.

*Inspector Comments:* Observed cyanuric acid level at above 100ppm in pool.

**Overall Inspection Comments**

No summary comments have been made for this inspection.