



**County of San Bernardino • Department of Public Health
Division of Environmental Health Services
COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

www.sbcounty.gov/dehs

(800) 442-2283

FACILITY NAME HILLSIDE APARTMENTS					DATE 7/17/2012	SIGNATURE	
LOCATION 2196 KENDALL DR, SAN BERNARDINO, CA 92407					REINSPECTION DATE 12/17/2012	PERMIT EXPIRATION 4/30/2013	
MAILING ADDRESS 2196 KENDALL DR, SAN BERNARDINO, CA 92407					<input checked="" type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input type="checkbox"/> ACCOUNT REHS Adela Evans		
FA # FA0005605	PR # PR0016270	SR # Not Specified	CO # Not Specified	PE 3601	PROGRAM IDENTIFIER: spa		
TIME IN 12:00 PM	TIME OUT 12:01 PM	CONTACT Not Captured			SERVICE: 003 - Inspection - Follow Up Inspection		
					RESULT: 03 - Corrective Action / No Follow up Required		
					ACTION: 15 - Permit Reinstated / Facility Re-opened		


RECREATIONAL HEALTH - PUBLIC POOL/SPA

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50

Recreational Health Details

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	40
volume (gal)	1,226
area (sq ft)	No Data
occupancy	7

Inspection Violations

No violations cited.

Overall Inspection Comments

Spa was initially closed on 6/11/12 due to gate not being completely self-closing and high chlorine levels. Upon re-inspection on 7/10/12, spa remained closed due to gate not being able to completely self-close. Upon routine inspection, gate was able to self-close and latch when opened at least 18 inches and chlorine levels had been corrected. Spa may be re-opened.

[EHS would appreciate your feedback on this inspection. Click here to take our survey or browse to surveymonkey.com/s/rehealthsurvey](#)