



**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM  
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

[www.sbcounty.gov/dehs](http://www.sbcounty.gov/dehs)

(800) 442-2283

FACILITY NAME <b>AYRES HOTEL</b>				DATE <b>6/13/2013</b>	SIGNATURE
LOCATION <b>4785 CHINO HILLS PKWY, CHINO HILLS, CA 91709</b>				REINSPECTION DATE <b>12/13/2013</b>	PERMIT EXPIRATION <b>6/30/2013</b>
MAILING ADDRESS <b>355 BRISTOL ST STE A, COSTA MESA CA 92626</b>				REHS <b>Tin Nguyen</b>	
FA # <b>FA0017188</b>	PR # <b>PR0023204</b>	SR # <b>Not Specified</b>	CO # <b>Not Specified</b>	PE <b>3601</b>	PROGRAM IDENTIFIER: POOL
TIME IN <b>10:46 AM</b>	TIME OUT <b>11:13 AM</b>	CONTACT <b>Not Captured</b>			SERVICE: 001 - Inspection - Routine
					RESULT: 03 - Corrective Action / No Follow up Required
					ACTION: 01 - No Further Action Required

**RECREATIONAL HEALTH - PUBLIC POOL/SPA**


Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

**98**

SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

**36K472 Access - Steps - Handrails - Diving Area**

**POINTS**  
**2**

Compliance Date: Not Specified  
Not In Compliance  
Violation Reference - CCR - 3111B,  
3113B

Inspector Comments: Observed hand rail at pool step loose. Repair/replace.

**Violation Description:** Stairs shall be provided in the shallowest portion of a pool. Ladders shall be corrosion resistant and shall be equipped with slip resistant tread surfaces. Ladders shall be rigidly installed. Hand rails shall be provided at the top of both sides of each ladder and recessed steps and shall extend over the coping or edge of the deck. Diving boards and platforms shall be anchored to the pool deck, constructed of corrosion resistant material, designed and constructed to be easily cleanable and finished with a durable slip resistant material.

**Overall Inspection Comments**

pH: 8.0  
Chlorine: 4.5 ppm  
CYA: 0 ppm  
Flow rate: 55 gpm

**Photo Attachments:**  
No Photo Attachments