



**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM  
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

(800) 442-2283

www.sbcounty.gov/dph/dehs

FACILITY NAME <b>COMFORT SUITES ONTARIO AIRPORT</b>				DATE <b>7/1/2013</b>	SIGNATURE
LOCATION <b>1811 E HOLT BL, ONTARIO, CA 91761</b>				REINSPECTION DATE <b>7/15/2013</b>	PERMIT EXPIRATION <b>2/28/2014</b>
MAILING ADDRESS <b>1811 E HOLT BL, ONTARIO CA 91761</b>				REHS <b>Sierra Clayborn</b>	
FA # <b>FA0016735</b>	PR # <b>PR0022411</b>	SR # <b>Not Specified</b>	CO # <b>Not Specified</b>	PE <b>3601</b>	PROGRAM IDENTIFIER: Spa SERVICE: 001 - Inspection - Routine
TIME IN <b>2:49 PM</b>	TIME OUT <b>3:30 PM</b>	CONTACT <b>Not Captured</b>			RESULT: 05 - Corrective Action / Follow up Required ACTION: 14 - Permit Suspd / Facility Closed fencing iss

**RECREATIONAL HEALTH - PUBLIC POOL/SPA**




Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

**88**

SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

Ideal
In Compliance
Not in Compliance



temperature (F)	103.6
observed flow (gpm)	No Data
required flow (gpm)	31
volume (gal)	937
area (sq ft)	50
occupancy	5

**36K995 Permit - Suspension**

**CRITICAL**

POINTS  
**NA**

Compliance Date: Not Specified  
Not In Compliance  
Violation Reference - HSC

Inspector Comments: Spa permit suspended due to gate not self-closing.

**Violation Description:** Violation(s) observed pose an immediate threat to public health and safety. The health permit to operate is hereby suspended and the pool/spa ordered closed until the listed violation(s) have been corrected and verified by Environmental Health Services (EHS). The facility is to remain closed until permission from EHS is given. Contact your inspector at your local office to schedule a reinspection to reinstate the health permit. The facility is posted closed; do not move, hide, or remove the sign. Reopening of the pool/spa without the approval by EHS, may result in an hourly billable Professional Services fee.

**36K438 Enclosure - Critical - Gates Drowning Hazard**

**CRITICAL**

POINTS  
**4**

Compliance Date: Not Specified  
Not In Compliance  
Violation Reference - HSC - 3119B

Inspector Comments: Observed 1 keyless egress not self-closing.

**Violation Description:** Gates and doors shall be equipped with self-closing and self-latching devices. The self-latching device shall keep the gate or door securely closed. Gates and doors shall open outwardly away from the pool except where otherwise prohibited by law. Gates and doors shall be capable of being locked during times when the pool is closed. The pool enclosure shall have at least one means of egress without a key for emergency purposes.

**36K412 Water Quality - Non-Critical - Free/Combined Disinfectant Level**

POINTS  
**2**

Compliance Date: Not Specified  
Not In Compliance  
Violation Reference - CCR - 65529

Inspector Comments: Observed chlorine at 0.5ppm.

**Violation Description:** For pools using hypochlorite or gaseous chlorine without a stabilizer, a free chlorine residual at least 1.0 ppm shall be maintained throughout the pool. If cyanuric acid or a chlorinated isocyanurate is used, a free chlorine residual of at least 1.5 ppm shall be maintained throughout the pool. Combined chlorine/disinfectant shall not exceed approved level.

**36K426 Safety - Emergency Shut-Off Switch**

POINTS  
**2**

Compliance Date: Not Specified  
Not In Compliance  
Violation Reference - CCR - 3138B

Inspector Comments: Observed emergency shut off switch disconnected from recirculation system. Reconnect immediately.

**Violation Description:** A clearly labeled emergency shut off switch for the control of both the recirculation system and the aeration and/or jet system shall be installed adjacent to the spa pool.



**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM  
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

(800) 442-2283

[www.sbcounty.gov/dph/dehs](http://www.sbcounty.gov/dph/dehs)

FACILITY NAME <b>COMFORT SUITES ONTARIO AIRPORT</b>	DATE <b>7/1/2013</b>	SIGNATURE
LOCATION <b>1811 E HOLT BL, ONTARIO, CA 91761</b>	REHS <b>Sierra Clayborn</b>	

**36K448 Equipment - Flow Meter**

<b>POINTS</b> <b>2</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b> Observed broken flow meter.
	Not In Compliance Violation Reference - CCR - 3125B	

**Violation Description:** A flow meter shall be provided on each recirculation system accurate to within 10 percent of flow. Flowmeter shall be maintained in good repair, accurately displaying flowrate.

**36K460 Skimmers - Requirements**

<b>POINTS</b> <b>2</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b> Observed missing weir gate.
	Not In Compliance Violation Reference - CCR - 65533, 3136B	

**Violation Description:** The pool shall be equipped with one or more skimming methods to provide continuous skimming of the pool water and shall be capable of continually withdrawing not less than 75 percent of the required flow rate. Skimmers and water levels shall be maintained and operated to remove floating scum, sputum or debris continuously. The skimmer shall be recessed into the pool wall, individually adjustable for the rate of flow with either an external or internal device, provided with an air lock protective device and provided with a removable and cleanable screen or basket to trap objects.

**Overall Inspection Comments**

No summary comments have been made for this inspection.

**Photo Attachments:**

No Photo Attachments