



County of San Bernardino • Department of Public Health
 Division of Environmental Health Services
COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

(800) 442-2283

www.sbcounty.gov/dph/dehs

| | | | | | |
|--|----------------------------|--------------------------------|------------------------------|---------------------------------------|--|
| FACILITY NAME FOOTHILL CAPE APTS | | | | DATE 7/12/2013 | SIGNATURE <i>Mary Hale</i> |
| LOCATION 16270 FOOTHILL , FONTANA, CA 92335 | | | | REINSPECTION DATE 1/12/2014 | PERMIT EXPIRATION 9/30/2013 |
| MAILING ADDRESS 16270 FOOTHILL , FONTANA, CA 92335 | | | | REHS Chris Nwadike | |
| FA # FA0004832 | PR # PR0016019 | SR # Not Specified | CO # Not Specified | PE 3601 | PROGRAM IDENTIFIER: pool |
| TIME IN 1:24 PM | TIME OUT 2:11 PM | CONTACT Not Captured | | | SERVICE: 001 - Inspection - Routine |
| | | | | | RESULT: 03 - Corrective Action / No Follow up Required |
| | | | | | ACTION: 01 - No Further Action Required |

RECREATIONAL HEALTH - PUBLIC POOL/SPA



Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

98

SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

| |
|-------------------|
| Ideal |
| In Compliance |
| Not in Compliance |



| | |
|---------------------|--------|
| temperature (F) | 84.0 |
| observed flow (gpm) | 60 |
| required flow (gpm) | 35 |
| volume (gal) | 12,480 |
| area (sq ft) | 416 |
| occupancy | 17 |

36K472 Access - Steps - Handrails - Diving Area

POINTS
2

Compliance Date: Not Specified
 Not In Compliance
 Violation Reference - CCR - 3111B,
 3113B

Inspector Comments: Observed a loose hand rail at the deep end.
 Tighten the hand rail.

Violation Description: Stairs shall be provided in the shallowest portion of a pool. Ladders shall be corrosion resistant and shall be equipped with slip resistant tread surfaces. Ladders shall be rigidly installed. Hand rails shall be provided at the top of both sides of each ladder and recessed steps and shall extend over the coping or edge of the deck. Diving boards and platforms shall be anchored to the pool deck, constructed of corrosion resistant material, designed and constructed to be easily cleanable and finished with a durable slip resistant material.

Overall Inspection Comments

No summary comments have been made for this inspection.

Photo Attachments:
 No Photo Attachments