



**County of San Bernardino • Department of Public Health
Division of Environmental Health Services
COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

(800) 442-2283

www.sbcounty.gov/dph/dehs

FACILITY NAME SONRISA HOMEOWNERS ASSOCIATION					DATE 7/15/2013	SIGNATURE	
LOCATION 13292 SUNNYSLOPE DR, CHINO HILLS, CA 91710					REINSPECTION DATE 1/16/2014	PERMIT EXPIRATION 6/30/2014	
MAILING ADDRESS PO BOX 5022, UPLAND CA 91785					REHS Tin Nguyen		
FA # FA0005220	PR # PR0015126	SR # Not Specified	CO # Not Specified	PE 3601	PROGRAM IDENTIFIER: Spa SERVICE: 001 - Inspection - Routine		
TIME IN 3:20 PM	TIME OUT 3:46 PM	CONTACT Not Captured			RESULT: 03 - Corrective Action / No Follow up Required ACTION: 01 - No Further Action Required		

RECREATIONAL HEALTH - PUBLIC POOL/SPA


Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

96

SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	36
volume (gal)	1,088
area (sq ft)	64
occupancy	6

36K446 Equipment - Chlorinator/Heater/Jets

POINTS 2	Compliance Date: Not Specified	Inspector Comments: Observed spa jet system not working. Repair/replace jet system in spa.
	Not In Compliance	
	Violation Reference - CCR - 65529, 65535, 3134B...	

Violation Description: Pools, when open or in use, shall be disinfected continuously by a chemical which imparts a residual effect. Disinfectant feeders shall comply with applicable requirements established by the NSF/ANSI 50-2010 performance standard effective August 2010 for disinfectant feeders. All feeders shall be capable of supplying not less than the equivalent of 3 pounds of 100 percent available chlorine per day per 10,000 gallons of pool water capacity. All parts of the pool and related pool facilities and equipment shall be maintained in good repair. A spa pool aeration and/or jet system shall be completely separate from the recirculation system and shall not be interconnected with any other pool.

36K466 Structure - Pool Shell

POINTS 2	Compliance Date: Not Specified	Inspector Comments: Observed spa steps chip. Ensure spa shell is smooth and non-abrasive.
	Not In Compliance	
	Violation Reference - CCR - 3108B	

Violation Description: The finished pool shell shall be lined with a smooth waterproof interior finish that will withstand repeated brushing, scrubbing, and cleaning procedures. The finish color shall be white. Tiles installed at the waterline shall be of contrasting color. A spa pool may be finished in a light color other than white when approved by the enforcing agent. Pool shell shall be maintained in good repair.

Overall Inspection Comments

pH: 7.0
Chlorine: 10.0 ppm
CYA: 55 ppm
Flow rate: n/a

NOTE:

-Please provide new code to enter pool/spa recirculation room. Code given does not open lock to pump room.

Photo Attachments:

No Photo Attachments