



County of San Bernardino • Department of Public Health  
 Division of Environmental Health Services  
**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM**  
**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

www.sbcounty.gov/dph/dehs

(800) 442-2283

FACILITY NAME <b>RESIDENCE INN BY MARRIOTT</b>					DATE <b>7/16/2013</b>	SIGNATURE	
LOCATION <b>2025 CONVENTION CENTER WY, ONTARIO, CA 91764</b>					REINSPECTION DATE <b>1/16/2014</b>	PERMIT EXPIRATION <b>8/31/2013</b>	
MAILING ADDRESS <b>50 COCONUT ROW STE 200, PALM BEACH FL 33480</b>					REHS <b>Sierra Clayborn</b>		
FA # <b>FA0006599</b>	PR # <b>PR0015913</b>	SR # <b>Not Specified</b>	CO # <b>Not Specified</b>	PE <b>3601</b>	PROGRAM IDENTIFIER: Spa		
TIME IN <b>11:37 AM</b>	TIME OUT <b>12:04 PM</b>	CONTACT <b>Not Captured</b>			SERVICE: 001 - Inspection - Routine		
					RESULT: 03 - Corrective Action / No Follow up Required		
					ACTION: 01 - No Further Action Required		

**RECREATIONAL HEALTH - PUBLIC POOL/SPA**




Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

**98**

SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

Ideal
In Compliance
Not in Compliance



temperature (F)	103.6
observed flow (gpm)	40
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

**36K460 Skimmers - Requirements**

**POINTS**  
**2**

Compliance Date: Not Specified  
 Not In Compliance  
 Violation Reference - CCR - 65533, 3136B

**Inspector Comments:** Observed basket broken. Replace.  
 Observed poor suction. Ensure that skimmer is able to provide 75 % of spa suction compared to main drains at 25% suction.  
 Observed damage to skimmer opening and walls. Repair by next pool season 2014.

**Violation Description:** The pool shall be equipped with one or more skimming methods to provide continuous skimming of the pool water and shall be capable of continually withdrawing not less than 75 percent of the required flow rate. Skimmers and water levels shall be maintained and operated to remove floating scum, sputum or debris continuously. The skimmer shall be recessed into the pool wall, individually adjustable for the rate of flow with either an external or internal device, provided with an air lock protective device and provided with a removable and cleanable screen or basket to trap objects.

**Overall Inspection Comments**

**NOTE:**  
 Inspector will return in one week to re-inspect the shower drain for proper drainage.

**Photo Attachments:**  
 No Photo Attachments