



County of San Bernardino • Department of Public Health
 Division of Environmental Health Services
COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

(800) 442-2283

www.sbcounty.gov/dph/dehs

FACILITY NAME HAMPTON INN & SUITES					DATE 7/24/2013	SIGNATURE <i>Robert J. Tentino</i>	
LOCATION 250 N 9TH ST, COLTON, CA 92324					REINSPECTION DATE 1/24/2014	PERMIT EXPIRATION 4/30/2014	
MAILING ADDRESS 105 DECKER CT STE 500, IRVING TX 75062					REHS John Babalola		
<input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input checked="" type="checkbox"/> ACCOUNT					PROGRAM IDENTIFIER: pool		
FA # FA0008659	PR # PR0014087	SR # Not Specified	CO # Not Specified	PE 3601	SERVICE: 001 - Inspection - Routine		
TIME IN 11:57 AM	TIME OUT 12:35 PM	CONTACT Not Captured			RESULT: 03 - Corrective Action / No Follow up Required		
					ACTION: 01 - No Further Action Required		

RECREATIONAL HEALTH - PUBLIC POOL/SPA



Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

96

SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	0
required flow (gpm)	40
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

36K448 Equipment - Flow Meter

POINTS
2

Compliance Date: Not Specified
 Not In Compliance
 Violation Reference - CCR - 3125B

Inspector Comments: Repair/replace the non-functional flow meter.

Violation Description: A flow meter shall be provided on each recirculation system accurate to within 10 percent of flow. Flowmeter shall be maintained in good repair, accurately displaying flowrate.

36K472 Access - Steps - Handrails - Diving Area

POINTS
2

Compliance Date: Not Specified
 Not In Compliance
 Violation Reference - CCR - 3111B, 3113B

Inspector Comments: Secure the unstable hand rails.

Violation Description: Stairs shall be provided in the shallowest portion of a pool. Ladders shall be corrosion resistant and shall be equipped with slip resistant tread surfaces. Ladders shall be rigidly installed. Hand rails shall be provided at the top of both sides of each ladder and recessed steps and shall extend over the coping or edge of the deck. Diving boards and platforms shall be anchored to the pool deck, constructed of corrosion resistant material, designed and constructed to be easily cleanable and finished with a durable slip resistant material.

Overall Inspection Comments

No summary comments have been made for this inspection.

Photo Attachments:

No Photo Attachments