



County of San Bernardino • Department of Public Health
 Division of Environmental Health Services
COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

(800) 442-2283

www.sbcounty.gov/dph/dehs

FACILITY NAME HILTON GARDEN INN SAN BERNARDINO					DATE 7/24/2013	SIGNATURE	
LOCATION 1755 S WATERMAN AV, SAN BERNARDINO, CA 92408					REINSPECTION DATE 1/24/2014	PERMIT EXPIRATION 7/31/2013	
MAILING ADDRESS 42 CORPORATE PARK STE 200, IRVINE CA 92606					REHS Yong Aday		
FA # FA0018426	PR # PR0024475	SR # Not Specified	CO # Not Specified	PE 3601	PROGRAM IDENTIFIER: POOL		
TIME IN 9:56 AM	TIME OUT 10:20 AM	CONTACT Not Captured			SERVICE: 001 - Inspection - Routine		
					RESULT: 03 - Corrective Action / No Follow up Required		
					ACTION: 01 - No Further Action Required		

RECREATIONAL HEALTH - PUBLIC POOL/SPA



Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

96

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

SCORE

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

36K448 Equipment - Flow Meter

POINTS	Compliance Date: Not Specified
2	Not In Compliance
	Violation Reference - CCR - 3125B

Inspector Comments: Observed stuck flow meter.

Violation Description: A flow meter shall be provided on each recirculation system accurate to within 10 percent of flow. Flowmeter shall be maintained in good repair, accurately displaying flowrate.

36K460 Skimmers - Requirements

POINTS	Compliance Date: Not Specified
2	Not In Compliance
	Violation Reference - CCR - 65533, 3136B

Inspector Comments: Replace missing weir gates for skimmers.

Violation Description: The pool shall be equipped with one or more skimming methods to provide continuous skimming of the pool water and shall be capable of continually withdrawing not less than 75 percent of the required flow rate. Skimmers and water levels shall be maintained and operated to remove floating scum, sputum or debris continuously. The skimmer shall be recessed into the pool wall, individually adjustable for the rate of flow with either an external or internal device, provided with an air lock protective device and provided with a removable and cleanable screen or basket to trap objects.

Overall Inspection Comments

Note: Provide safety signs according to the new signage requirement. A letter regarding the new requirement was sent out by this dept. The information is also available on our website: www.sbcounty.gov/dph/dehs

Photo Attachments:

No Photo Attachments