



County of San Bernardino • Department of Public Health
 Division of Environmental Health Services
COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT




(800) 442-2283

www.sbcounty.gov/dph/dehs

FACILITY NAME BEST WESTERN ONTARIO AIRPORT				DATE 7/31/2013	SIGNATURE
LOCATION 209 N VINEYARD AV, ONTARIO, CA 91764				REINSPECTION DATE 12/31/2013	PERMIT EXPIRATION 1/31/2014
MAILING ADDRESS 209 N VINEYARD AV, ONTARIO CA 91764				REHS Sierra Clayborn	
FA # FA0008456	PR # PR0014532	SR # Not Specified	CO # Not Specified	PE 3601	PROGRAM IDENTIFIER: Spa
TIME IN 4:01 PM	TIME OUT 4:25 PM	CONTACT Not Captured			SERVICE: 003 - Inspection - Follow Up Inspection
					RESULT: 03 - Corrective Action / No Follow up Required
					ACTION: 15 - Permit Reinstated / Facility Re-opened

RECREATIONAL HEALTH - PUBLIC POOL/SPA

Ideal
In Compliance
Not in Compliance



temperature (F)	102.7
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

36K992 Permit Reinstatement

POINTS
NA

Compliance Date: Not Specified
 Not In Compliance
 Violation Reference - HSC

Inspector Comments:

Violation Description: The health permit to operate is hereby reinstated and facility may open.

36K994 Reinspection

POINTS
NA

Compliance Date: Not Specified
 Not In Compliance
 Violation Reference - HSC

Inspector Comments: During routine inspection, observed chlorine at 23ppm and pH at 7.1. Observed GFCI not working during inspection.

Violation Description: Reinspection conducted at this time to determine compliance from prior inspection.

Overall Inspection Comments

Observed chlorine at 11.5ppm. Ensure to not exceed 10ppm.
 Observed functioning GFCI for spa, but not for pool. Install GFCI for pool before pool season 2014.

Spa permit reinstated; pool/spa area open for use.

Photo Attachments:

No Photo Attachments