



**County of San Bernardino • Department of Public Health
Division of Environmental Health Services
COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**


www.sbcounty.gov/dph/dehs

(800) 442-2283

FACILITY NAME CENTURY VILLAGE RIALTO EAST				DATE 8/5/2013	SIGNATURE
LOCATION 588 W VIRGINIA DR, RIALTO, CA 92377				REINSPECTION DATE 8/19/2013	PERMIT EXPIRATION 6/30/2014
MAILING ADDRESS 14780 PIPELINE AV, CHINO HILLS CA 91709				REHS Breyanna Lyles	
FA # FA0008367	PR # PR0014597	SR # Not Specified	CO # Not Specified	PE 3601	PROGRAM IDENTIFIER: Pool
TIME IN 1:59 PM	TIME OUT 4:52 PM	CONTACT Not Captured			SERVICE: 003 - Inspection - Follow Up Inspection
				RESULT: 05 - Corrective Action / Follow up Required	
				ACTION: 14 - Permit Suspd / Facility Closed fencing iss	

RECREATIONAL HEALTH - PUBLIC POOL/SPA

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	40

36K995 Permit - Suspension



POINTS
NA

Compliance Date: Not Specified
Not In Compliance
Violation Reference - HSC

Inspector Comments: During the follow-up inspection it was observed that the original gap in the fence, measuring 8 inches, was not repaired and that the gap is now larger (measuring 13 inches) due to an additional missing bar. It was observed that the original "Pool Closure" sign was missing. Another "Pool Closure" sign was posted at entry to pool. Maintain fencing/enclosure with no gaps larger than 4 inches. Permit has been inactivated and pool is to remain closed until gap/hole in fence is repaired. Contact inspector/health department prior to re-opening.

During the follow-up inspection multiple calls were made to home owners association to determine if the fencing could be repaired immediately and while inspector was on site. Inspector stayed on site until association could be reached. The HA's management determined that the fencing could not be repaired until approximately 5:30pm, and that until that time the management would provide a security officer to ensure that no residents would access the pool unsafely. Inspector stayed on site until security officer (Mr. Castro) arrived to pool facility at 4:45pm. The HA's management has been made aware of the safety risk due to missing bars in the fencing, and will have security on site until the fencing is repaired and has no holes/gaps greater than 4 inches.

Violation Description: Violation(s) observed pose an immediate threat to public health and safety. The health permit to operate is hereby suspended and the pool/spa ordered closed until the listed violation(s) have been corrected and verified by Environmental Health Services (EHS). The facility is to remain closed until permission from EHS is given. Contact your inspector at your local office to schedule a reinspection to reinstate the health permit. The facility is posted closed; do not move, hide, or remove the sign. Reopening of the pool/spa without the approval by EHS, may result in an hourly billable Professional Services fee.

36K436 Enclosure - Critical - Enclosure Drowning Hazard



POINTS
4

Compliance Date: Not Specified
Not In Compliance
Violation Reference - CCR 24 - 3119B

Inspector Comments: During the routine inspection there was a bar missing in the enclosure, creating a gap of 8 inches. Pool had been closed on 7/17/13

During the follow-up inspection there was an additional bar missing creating a gap measuring 13 inches. Maintain enclosure with no gaps or holes larger than 4 inches wide.

Violation Description: The pool shall be enclosed by one or a combination of the following: a fence; portion of a building; wall; or other approved durable enclosure. Doors, windows gates of living units or associated private premises shall not be permitted as part of the pool enclosure. The enclosure shall have a minimum effective perpendicular height of 5 feet. Openings, holes or gaps in the enclosure, doors and/or gates shall not allow the passage of a 4-inch diameter sphere. The enclosure shall be constructed over a hard and permanent material equivalent to concrete. The enclosure shall be designed and constructed so that it cannot be readily climbed by small children.

36K482 Restrooms - Toilet Facilities - Showers - Drinking Fountain

POINTS
2

Compliance Date: Not Specified
Not In Compliance
Violation Reference - CCR - 65535, 65551, 3117B

Inspector Comments: Observed restrooms with odor and in unclean condition. Observed feces outside of restroom. Clean and maintain restroom and surrounding area.

Violation Description: Toilets, urinals, showers, wash basins and other plumbing fixtures shall be maintained in a clean condition, and in good repair. For shower, toilet and dressing facilities, the walls, partitions, doors, lockers and similar surfaces which require periodic cleaning shall be maintained smooth and finished so as to facilitate cleaning. Showers shall be provided with soap in soap dispensers or containers. For toilet facilities, handwashing detergent or soap, sanitary towels or hot air blowers, and toilet tissues shall be provided in permanently installed dispensing devices. Showers and lavatories shall be provided with hot and cold water faucets.

One guarded jet drinking fountain shall be provided for the first 250 bathers and an additional fountain shall be provided for each additional 200 bathers or fraction thereof.

Overall Inspection Comments



**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

www.sbcounty.gov/dph/dehs

(800) 442-2283

FACILITY NAME CENTURY VILLAGE RIALTO EAST	DATE 8/5/2013	SIGNATURE 
LOCATION 588 W VIRGINIA DR, RIALTO, CA 92377	REHS Breyanna Lyles	

No summary comments have been made for this inspection.

Photo Attachments:

No Photo Attachments