



**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**



(800) 442-2283

www.sbcounty.gov/dph/dehs

FACILITY NAME CENTURY VILLAGE RIALTO EAST					DATE 8/13/2013	SIGNATURE	
LOCATION 588 W VIRGINIA DR, RIALTO, CA 92377					REINSPECTION DATE 8/27/2013	PERMIT EXPIRATION 6/30/2014	
MAILING ADDRESS 14780 PIPELINE AV, CHINO HILLS CA 91709					<input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input checked="" type="checkbox"/> ACCOUNT REHS Breyanna Lyles		
FA # FA0008367	PR # PR0014597	SR # Not Specified	CO # Not Specified	PE 3601	PROGRAM IDENTIFIER: Pool		
TIME IN 4:03 PM	TIME OUT 4:48 PM	CONTACT Not Captured			SERVICE: 003 - Inspection - Follow Up Inspection		
					RESULT: 05 - Corrective Action / Follow up Required		
					ACTION: 14 - Permit Suspd / Facility Closed fencing iss		

RECREATIONAL HEALTH - PUBLIC POOL/SPA

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	40

36K995 Permit - Suspension



POINTS NA	Compliance Date: Not Specified	Inspector Comments: Permit is suspended and pool closed until there are no gaps over 4 inches in the enclosure.
	Not In Compliance	
	Violation Reference - HSC	

Violation Description: Violation(s) observed pose an immediate threat to public health and safety. The health permit to operate is hereby suspended and the pool/spa ordered closed until the listed violation(s) have been corrected and verified by Environmental Health Services (EHS). The facility is to remain closed until permission from EHS is given. Contact your inspector at your local office to schedule a reinspection to reinstate the health permit. The facility is posted closed; do not move, hide, or remove the sign. Reopening of the pool/spa without the approval by EHS, may result in an hourly billable Professional Services fee.

36K438 Enclosure - Critical - Gates Drowning Hazard



POINTS 4	Compliance Date: Not Specified	Inspector Comments: During the previous inspection it was observed that there were multiple bars missing in the enclosure causing there to be a gap measuring over 4 inches. During this inspection it was observed that missing bars had been replaced. It was observed that one bar was bent (towards the bottom) causing there to still be a gap measuring over 4 inches. Enclosure must still be repaired so that there are no gaps measuring over 4 inches. Permit is inactivated and pool closed until there are no gaps measuring over 4 inches.
	Not In Compliance	
	Violation Reference - HSC - 3119B	

Violation Description: Gates and doors shall be equipped with self-closing and self-latching devices. The self-latching device shall keep the gate or door securely closed. Gates and doors shall open outwardly away from the pool except where otherwise prohibited by law. Gates and doors shall be capable of being locked during times when the pool is closed. The pool enclosure shall have at least one means of egress without a key for emergency purposes.

Overall Inspection Comments

No summary comments have been made for this inspection.

Photo Attachments:

No Photo Attachments