



County of San Bernardino • Department of Public Health
 Division of Environmental Health Services
COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

(800) 442-2283

www.sbcounty.gov/dph/dehs

FACILITY NAME REDLANDS HIGH SCHOOL					DATE 8/27/2013	SIGNATURE	
LOCATION 840 E CITRUS AV, REDLANDS, CA 92373					REINSPECTION DATE 2/27/2014	PERMIT EXPIRATION	
MAILING ADDRESS 840 E CITRUS AV, REDLANDS, CA 92373					REHS Eurich Santiago		
<input checked="" type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input type="checkbox"/> ACCOUNT					PROGRAM IDENTIFIER: Deep Pool		
FA # FA0006492	PR # PR0014837	SR # Not Specified	CO # Not Specified	PE 3603	SERVICE: 001 - Inspection - Routine		
TIME IN 11:31 AM	TIME OUT 12:03 PM	CONTACT Not Captured			RESULT: 03 - Corrective Action / No Follow up Required		
					ACTION: 01 - No Further Action Required		

RECREATIONAL HEALTH - PUBLIC SCHOOL POOL / SPA



Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

98

SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	590
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

36K472 Access - Steps - Handrails - Diving Area

POINTS
2

Compliance Date: Not Specified
 Not In Compliance
 Violation Reference - CCR - 3111B,
 3113B

Inspector Comments: Observed loose handrails at pool area. Ensure all handrails are tightly fitted.

Violation Description: Stairs shall be provided in the shallowest portion of a pool. Ladders shall be corrosion resistant and shall be equipped with slip resistant tread surfaces. Ladders shall be rigidly installed. Hand rails shall be provided at the top of both sides of each ladder and recessed steps and shall extend over the coping or edge of the deck. Diving boards and platforms shall be anchored to the pool deck, constructed of corrosion resistant material, designed and constructed to be easily cleanable and finished with a durable slip resistant material.

Overall Inspection Comments

No summary comments have been made for this inspection.

Photo Attachments:
 No Photo Attachments