



**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

(800) 442-2283

www.sbcounty.gov/dph/dehs

| | | | | | | |
|----------------------------------------------------------------|----------------------------|--------------------------------|------------------------------|----------------------------------------|-----------------------------------------------------|--|
| FACILITY NAME COUNTRY INN | | | | DATE 10/4/2013 | SIGNATURE | |
| LOCATION 606 N H ST, SAN BERNARDINO, CA 92410 | | | | REINSPECTION DATE 10/07/2013 | PERMIT EXPIRATION 5/31/2014 | |
| MAILING ADDRESS 606 N H ST, SAN BERNARDINO, CA 92410 | | | | REHS Bennetta Betbadal | | |
| FA # FA0008824 | PR # PR0013491 | SR # Not Specified | CO # Not Specified | PE 3601 | PROGRAM IDENTIFIER: Spa | |
| TIME IN 3:00 PM | TIME OUT 3:28 PM | CONTACT Not Captured | | | SERVICE: 006 - FIELD CONSULTATION | |
| | | | | | RESULT: 05 - CORRECTIVE ACTION / FOLLOW UP REQUIRED | |
| | | | | | ACTION: 03 - REINSPECTION REQUIRED | |

RECREATIONAL HEALTH - PUBLIC POOL/SPA

| |
|-------------------|
| Ideal |
| In Compliance |
| Not in Compliance |



| | |
|---------------------|---------|
| temperature (F) | No Data |
| observed flow (gpm) | No Data |
| required flow (gpm) | No Data |
| volume (gal) | No Data |
| area (sq ft) | No Data |
| occupancy | No Data |

No Violations Cited

Overall Inspection Comments

Observed spa is still drained.

If owner wishes to reopen the spa must submit plans and pool has to be up to current pool code since it has been closed since 7-2011

Following corrections must be addressed during plan check process:

- 1- Main drain shall be split (minimum of 3 ft between covers and hydraulically balanced and symmetrically plumbed)
- 2-Two 3-bend handrail to be added at the stairs and must be bonded to re-bar (building and safety plan approval)
- 3- Clear depth markers on the decking
- 4- Equalizer line might be required to be split 3 feet apart
- 5-Coping must be repaired

AB1020 form was approved with A.O Smith Guardian Motor BG128A added to Hayward pump. This set up is not approved since retrofit date for AB1020 has passed. In order to keep the current setting without splitting the main drain pipes, owner must obtain a written approval from pump manufacture (Hayward) that addition of A.O Smith motor does not alter the pumps' intended use.

Photo Attachments:

No Photo Attachments