



**County of San Bernardino • Department of Public Health
Division of Environmental Health Services
COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

www.sbcounty.gov/dph/dehs

(800) 442-2283

| | | | | | | | |
|---|-----------------------------|--------------------------------|------------------------------|-------------------|---|--|--|
| FACILITY NAME LA FITNESS | | | | | DATE 2/19/2014 | SIGNATURE | |
| LOCATION 784 E HOSPITALITY LN, SAN BERNARDINO, CA 92460 | | | | | REINSPECTION DATE 8/19/2014 | PERMIT EXPIRATION 11/30/2014 | |
| MAILING ADDRESS PO BOX 52110, IRVINE CA 92619 | | | | | REHS James Gutman | | |
| FA # FA0001333 | PR # PR0015754 | SR # Not Specified | CO # Not Specified | PE 3601 | PROGRAM IDENTIFIER: Pool | | |
| TIME IN 12:00 PM | TIME OUT 12:48 PM | CONTACT Not Captured | | | SERVICE: 001 - INSPECTION - ROUTINE | | |
| | | | | | RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP REQ | | |
| | | | | | ACTION: 01 - NO FURTHER ACTION REQUIRED | | |



RECREATIONAL HEALTH - PUBLIC POOL

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

96

SCORE



| | |
|---------------------|---------|
| temperature (F) | 85.0 |
| observed flow (gpm) | 75 |
| required flow (gpm) | No Data |
| volume (gal) | No Data |
| area (sq ft) | No Data |
| occupancy | No Data |

36K446 Equipment - Chlorinator/Heater/Jets

| | | |
|---------------------------|--|--|
| POINTS 2 | Compliance Date: Not Specified | Inspector Comments: Observed disinfectant feed line leaking. Replace feed line. |
| | Not In Compliance | |
| | Violation Reference - CCR - 65529, 65535, 3134B... | |

Violation Description: Pools, when open or in use, shall be disinfected continuously by a chemical which imparts a residual effect. Disinfectant feeders shall comply with applicable requirements established by the NSF/ANSI 50-2010 performance standard effective August 2010 for disinfectant feeders. All feeders shall be capable of supplying not less than the equivalent of 3 pounds of 100 percent available chlorine per day per 10,000 gallons of pool water capacity. All parts of the pool and related pool facilities and equipment shall be maintained in good repair. A spa pool aeration and/or jet system shall be completely separate from the recirculation system and shall not be interconnected with any other pool.

36K460 Skimmers - Requirements

| | | |
|---------------------------|--|--|
| POINTS 2 | Compliance Date: Not Specified | Inspector Comments: Observed weir gate missing in one skimmer. Replace weir gate. |
| | Not In Compliance | |
| | Violation Reference - CCR - 65533, 3136B | |

Violation Description: The pool shall be equipped with one or more skimming methods to provide continuous skimming of the pool water and shall be capable of continually withdrawing not less than 75 percent of the required flow rate. Skimmers and water levels shall be maintained and operated to remove floating scum, sputum or debris continuously. The skimmer shall be recessed into the pool wall, individually adjustable for the rate of flow with either an external or internal device, provided with an air lock protective device and provided with a removable and cleanable screen or basket to trap objects.

Overall Inspection Comments

Observed the direction of flow not labeled on recirculation system plumbing. Label pipes with the direction of flow.

Photo Attachments:

No Photo Attachments