



County of San Bernardino • Department of Public Health
 Division of Environmental Health Services
COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

www.sbcounty.gov/dph/dehs

(800) 442-2283

FACILITY NAME HILLCREST MOBILE ESTATES					DATE 8/20/2014	SIGNATURE	
LOCATION 33600 CALIMESA BL, YUCAIPA, CA 92399					REINSPECTION DATE Not Specified	PERMIT EXPIRATION 12/31/2014	
MAILING ADDRESS 33600 CALIMESA BL, YUCAIPA, CA 92399					REHS Robert Adams		
FA # FA0007160	PR # PR0014724	SR # Not Specified	CO # Not Specified	PE 3623	PROGRAM IDENTIFIER: Spa		
TIME IN 11:50 AM	TIME OUT 1:04 PM	CONTACT Not Captured			SERVICE: 001 - INSPECTION - ROUTINE		
					RESULT: 05 - CORRECTIVE ACTION / FOLLOW UP REQUIRED		
					ACTION: 03 - REINSPECTION REQUIRED		

RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility



Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

96

SCORE

Ideal
In Compliance
Not in Compliance



temperature (F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	10
volume (gal)	5,000
area (sq ft)	160
occupancy	8

36K406 Water Quality - Critical - pH High/Low



POINTS
4

Compliance Date: Not Specified
 Not In Compliance
 Violation Reference - CCR - 65529

Inspector Comments: Ph observed at 8.1. Technician on site corrected this to 7.0. Maintain spa pH between 7.2 and 8.0.

Violation Description: Water shall be maintained in an alkaline condition at a pH between 7.2 and 8.0.

Overall Inspection Comments

Chlorine 2.6ppm
 pH 7.0
 Cyanurates = 4.8ppm.

Observed booster pump with no dedicated drain cover. Unable to determine source of water for booster pump. Suspected source is under the same drain cover as the main line suction for the filtration. If so this would not meet AB 1020 compliance. Determine where the water source is and contact Robert Adams at 800-442-2283 within one week of this inspection. Failure to comply or a water source from the single drain cover will result in spa closure until VGB compliance is met.

Photo Attachments:
 No Photo Attachments