





County of San Bernardino • Department of Public Health
 Division of Environmental Health Services
COMMUNITY ENVIRONMENTAL HEALTH PROGRAM
RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

www.sbcounty.gov/dph/dehs

(800) 442-2283

FACILITY NAME VILLAGE OAKS APARTMENTS				DATE 1/9/2015	SIGNATURE
LOCATION 15773 HIGH KNOLL DR, CHINO HILLS, CA 91709				REINSPECTION DATE Not Specified	PERMIT EXPIRATION 6/30/2015
MAILING ADDRESS 15773 HIGH KNOLL DR, CHINO HILLS, CA 91709				REHS Veronica Martinez	
FA # FA0005109	PR # PR0015983	SR # Not Specified	CO # Not Specified	PE 3623	PROGRAM IDENTIFIER: Spa - South
TIME IN 5:00 PM	TIME OUT 5:44 PM	CONTACT Not Captured			SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION
					RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP REQ
					ACTION: 15 - PERMIT REINSTATED / FACILITY RE-OPENED

RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility



temperature (F)	61.0
observed flow (gpm)	No Data
required flow (gpm)	68
volume (gal)	2,050
area (sq ft)	78
occupancy	8

36K992 Permit Reinstatement

POINTS NA	Compliance Date: Not Specified	Inspector Comments: Observed the elimination of climbing risk by the installation of metal mesh on fencing behind both BBQ within the pool enclosure. Observed rusted and disconnected vertical support beams at their base on the east side of the pool enclosure repaired along fencing and matching current construction design. Observed pool skimmers functioning. Upon reinspection, above violations observed corrected and in compliance. The health permit is therefore reinstated and the spa reopened. NOTE: Observed no valve available allowing for the ability to use the skimmer at 100% for vacuuming the pool or spa or for returning back to less than 100% to allow for main drain suction for use in the filtration process. Contact Plan Check Department at 1(800) 442-2283 before required valve equipment is repaired or replaced.
	Not In Compliance Violation Reference - HSC	

Violation Description: The health permit to operate is hereby reinstated and facility may open.

Overall Inspection Comments

Observed the elimination of climbing risk by the installation of metal mesh on fencing behind both BBQ within the pool enclosure.

Observed rusted and disconnected vertical support beams at their base on the east side of the pool enclosure repaired along fencing and matching current construction design.

Observed pool skimmers functioning.

Upon reinspection, above violations observed corrected and in compliance. The health permit is therefore reinstated and the spa reopened.

NOTE: Observed no valve available allowing for the ability to use the skimmer at 100% for vacuuming the pool or spa or for returning back to less than 100% to allow for main drain suction for use in the filtration process. Contact Plan Check Department at 1(800) 442-2283 before required valve equipment is repaired or replaced.

Photo Attachments:

No Photo Attachments