



Public Health
Environmental Health Services

www.SBCounty.gov

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME COUNTRY SUITES BY AYRES		DATE 4/30/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 12/31/2015
LOCATION 1945 E HOLT BL, ONTARIO, CA 91764			INSPECTOR John Ramos	
MAILING ADDRESS 1945 E HOLT BL, ONTARIO, CA 91764			IDENTIFIER: Pool	
<input checked="" type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input type="checkbox"/> ACCOUNT			SERVICE: 001 - INSPECTION - ROUTINE	
TIME IN 9:42 AM	TIME OUT 10:20 AM	FACILITY ID FA0002473	RELATED ID PR0015587	PE 3620
			RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE	
			ACTION: 01 - NO FURTHER ACTION REQUIRED	



RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

100
SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

Ideal
In Compliance
Not in Compliance



temperature (°F)	77.0
observed flow (gpm)	50
required flow (gpm)	123
volume (gal)	46,037
area (sq ft)	536
occupancy	30

36K548 Equipment - Recirculation system components

POINTS NA	Compliance Date: Not Specified	Inspector Comments: Observed return line fittings removed from the pool. Install to provide efficient water circulation.
	Not In Compliance	
	Violation Reference - CCR - 3123B, 3138B	

Violation Description: Each pool shall be provided with a separate recirculation system designed for the continuous recirculation, filtration and disinfection of the pool water. The system shall consist of pumps, filters, chemical feeders, skimmers or perimeter overflow systems, valves, pipes, connections, fittings and appurtenances.

A spa pool aeration and/or jet system shall be completely separate from the recirculation system and shall not be interconnected with any other pool.

Overall Inspection Comments

No other problems were observed.

Signature(s) of Acknowledgement

NAME:
TITLE:

Total # of Images: 0