



RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME VILLA GABRIEL HOA			REINSPECTION DATE Not Specified	INSPECTOR Michelle Lamont	DATE 9/20/2016
LOCATION 8300 GABRIEL DR, RANCHO CUCAMONGA, CA 91730			PERMIT EXPIRATION 10/31/2016	IDENTIFIER: Spa SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE ACTION: 15 - PERMIT REINSTATED / FACILITY RE-OPEN	
TIME IN 4:00 PM	TIME OUT 4:15 PM	FACILITY ID FA0004427	RELATED ID PR0015419	PE 3623	


RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	61
volume (gal)	1,851
area (sq ft)	90
occupancy	9

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

- Meet the latest ANSI/APSP-16 performance standard
- Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K994 Reinspection

POINTS
NA

Compliance Date: Not Specified
Not In Compliance
Violation Reference - HSC

Inspector Comments: This follow-up inspection is being conducted because the pool was closed for high pH.
Today the pH was tested + found to be 7.99. The pool was reopened.
Maintain the pH between 7.2 + 8.0.
Water Clarity - good
Gates - self closing + self latching

The manager was informed via telephone regarding his pool being reopened + the results of this inspection.

Description: Reinspection conducted at this time to determine compliance from prior inspection.

Overall Inspection Comments

No summary comments have been made for this inspection.

Signature(s) of Acknowledgement

SNA

NAME:
TITLE:

Total # of Images: 0