



Public Health
Environmental Health Services

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

| | | | | |
|--|----------------------|--------------------------|--|--------------------------------|
| FACILITY NAME MT VIEW PARK CONDOS | | DATE 8/5/2015 | REINSPECTION DATE Not Specified | PERMIT EXPIRATION 6/30/2016 |
| LOCATION 149 W 6TH ST, SAN BERNARDINO, CA 92401 | | | INSPECTOR Chris Nwadike | |
| MAILING ADDRESS 180 W HIGHLAND AVE, SAN BERNARDINO CA 92405 | | | IDENTIFIER: Spa | |
| TIME IN 10:50 AM | TIME OUT 11:23 AM | FACILITY ID FA0008859 | RELATED ID PR0014214 | PE 3623 |
| | | | SERVICE: 001 - INSPECTION - ROUTINE RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE ACTION: 01 - NO FURTHER ACTION REQUIRED | |

RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$4.08 per 1 minute with a minimum time of 30 minutes, and a minimum charge of \$122.50.



94

SCORE

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

| |
|-------------------|
| Ideal |
| In Compliance |
| Not in Compliance |



| | |
|---------------------|---------|
| temperature (°F) | 88.0 |
| observed flow (gpm) | 0 |
| required flow (gpm) | No Data |
| volume (gal) | No Data |
| area (sq ft) | No Data |
| occupancy | No Data |

IMPORTANT: Replacement of Suction Outlet Covers
 Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

- Meet the latest ANSI/APSP-16 performance standard
- Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K502 Water Quality - Critical – Disinfectant level ⚠ CRITICAL ⚠

| | | |
|---------------------------|-----------------------------------|---|
| POINTS 5 | Compliance Date: Not Specified | Inspector Comments: Observed chlorine level at 0.25ppm. Maintain chlorine level between 2.0ppm and 10.0ppm. Corrected to 4.8ppm during inspection. |
| | Not In Compliance | |
| | Violation Reference - HSC - 65529 | |

Violation Description: The minimum concentration of disinfectant residual in public pools shall be 1.0 ppm free-chlorine without cyanuric acid or 2.0 ppm free-chlorine with cyanuric acid. The minimum concentration of disinfectant residual in public spas, wading pools, and spray grounds shall be 3.0 ppm free-chlorine. The maximum concentration of disinfectant residual shall be 10.0 ppm free-chlorine.

The minimum concentration of bromine residual in public pools shall be 2.0 ppm. The minimum concentration of bromine residual in public spas, wading pools, and spray grounds shall be 4.0 ppm.

A spray ground and water features with an ultraviolet light disinfection system shall be disinfected continuously at a minimum of 40 mJ/cm2 by the ultraviolet light disinfection units while the spray ground and water features are in use. If the ultraviolet dosage rate drops below 40 mJ/cm2 the operator shall close the spray ground and water features.

36K552 Equipment - Flow meter provided

| | | |
|---------------------------|--|--|
| POINTS 1 | Compliance Date: Not Specified | Inspector Comments: Observed no flow meter connection to the recirculation system. Flow meter must be installed on the pipe line leaving the filter and going into the spa (effluent line). |
| | Not In Compliance | |
| | Violation Reference - CCR 24 - 3125B.3 | |

Violation Description: A flow meter shall be provided on each recirculation system accurate to within 10 percent of flow and installed according to the manufacturer's written instructions with increments in the range of normal flow.

Overall Inspection Comments

No summary comments have been made for this inspection.

Signature(s) of Acknowledgement



Public Health
Environmental Health Services

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

| | |
|--|----------------------------|
| FACILITY NAME MT VIEW PARK CONDOS | DATE 8/5/2015 |
| LOCATION 149 W 6TH ST, SAN BERNARDINO, CA 92401 | INSPECTOR Chris Nwadike |

NAME:
TITLE:

Total # of Images: 0