



**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**



FACILITY NAME <b>EUREKA MANOR</b>		REINSPECTION <b>Not Specified</b>	INSPECTOR <b>Anies Kondoker</b>	DATE <b>9/25/2015</b>
LOCATION <b>1525 E EUREKA ST, SAN BERNARDINO, CA 92404</b>		PERMIT .....	IDENTIFIER: None	
TIME IN <b>8:55 AM</b>	TIME OUT <b>9:23 AM</b>	FACILITY ID <b>FA0008381</b>	RELATED ID <b>CO0052293</b>	PE <b>3620</b>
		SERVICE: 004 - COMPLAINT - INITIAL		
		RESULT: 05 - CORRECTIVE ACTION / FOLLOW UP REQUIRED		
		ACTION: 13 - PERMIT SUSPENDED / FACILITY CLOSED		

**RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility**

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

**IMPORTANT: Replacement of Suction Outlet Covers**  
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

- Meet the latest ANSI/APSP-16 performance standard
- Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your

**36K999 Complaint Inspection**

<b>POINTS</b> <b>NA</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b>
	Not In Compliance	
	Violation Reference - HSC	

**Description:** A complaint report has been received by Environmental Health.

**36K514 Water Quality – Critical – Water clarity** ⚠️ **CRITICAL** ⚠️

<b>POINTS</b> <b>5</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b> Observed pool water to be dark green. Bottom of the pool is not visible from pool deck. Observed debris accumulation on pool surface. Observed water level reaching pool coping.  Observed bottom of spa visible from pool deck. Observed debris accumulation on pool bottom.  Ensure to achieve good water clarity. Bottom of the pool and spa shall be easily visible from pool deck.
	Not In Compliance	
	Violation Reference - HSC - 65527	

**Violation Description:** The pool operator shall maintain clear pool water while the public pool is in use. The pool operator shall close the public pool if the bottom of the pool at the maximum depth is not clearly visible from the deck. The pool operator shall not reopen the public pool for use until the pool water is clean and clear, and the bottom of the pool at the maximum depth is clearly visible from the deck. If the bottom of the pool is not visible 48 hours following inspection and closure by the enforcing agent, the enforcing agent may order the pool drained.

**Overall Inspection Comments**



### RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME EUREKA MANOR	DATE 9/25/2015
LOCATION 1525 E EUREKA ST, SAN BERNARDINO, CA 92404	INSPECTOR Anies Kondoker

A complaint alleged that pool and spa was green.

**Findings:**

- Both gates are padlocked.
- Bottom of spa is visible from pool deck. Observed debris accumulation on spa bottom.
- Bottom of pool is not visible from pool deck.

Observed pool water to be dark green with water level reaching to pool coping. Observed floating debris on pool water.

**Corrective action (choose one):**

1. Bring water clarity in both pool and spa to meet pool code.

Bottom of pool and spa shall be easily visible from pool deck. Pump shall be fully operational and pH and free chlorine level shall be within legal limit.

2. Drain both pool and spa.

Failure to meet one of the options above by Monday 9/28/15 at 5 pm will result in a charged inspection or legal action.

### Signature(s) of Acknowledgement

NAME:

TITLE:

Total # of Images: 0