



Public Health
Environmental Health Services

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME INN AT SILVER LAKES		DATE 8/10/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 12/31/2015
LOCATION 14818 CLUBHOUSE DR, HELENDALE, CA 92342			INSPECTOR Melissa Nano	
MAILING ADDRESS PO BOX 299, HELENDALE CA 92342			IDENTIFIER: Large Pool	
TIME IN 2:29 PM			SERVICE: 001 - INSPECTION - ROUTINE	
TIME OUT 3:04 PM			RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE	
FACILITY ID FA0007283			ACTION: 01 - NO FURTHER ACTION REQUIRED	
RELATED ID PR0015589			PE 3620	

RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$4.08 per 1 minute with a minimum time of 30 minutes, and a minimum charge of \$122.50.




98

SCORE

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	75
volume (gal)	27,000
area (sq ft)	800
occupancy	40

IMPORTANT: Replacement of Suction Outlet Covers
 Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

- Meet the latest ANSI/APSP-16 performance standard
- Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K518 Water Quality – Cyanuric acid concentration

POINTS 1	Compliance Date: Not Specified	Inspector Comments: Maintain a cyanuric acid concentration no more than 100ppm. Observed concentration exceed 100ppm.
	Not In Compliance	
	Violation Reference - HSC - 65530	

Violation Description: The maximum concentration of cyanuric acid in public pool water shall not exceed 100.0 ppm.

36K526 Safety - Emergency shut-off switch

POINTS 1	Compliance Date: Not Specified	Inspector Comments: Obtain and post the following missing sign(s): 1. Local Emergency 2. Facility name and address
	Not In Compliance	
	Violation Reference - CCR 24 - 3138B.5	

Violation Description: A clearly labeled emergency shut off switch for the control of both the recirculation system and the aeration and/or jet system shall be installed adjacent to the spa pool.

Overall Inspection Comments

If there are any questions, please contact Environmental Health Services or Melissa Nano at (800) 442-2283.

Signature(s) of Acknowledgement

NAME: refer to pool OIR (Todd)
 TITLE:



Public Health
Environmental Health Services

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME INN AT SILVER LAKES	DATE 8/10/2015
LOCATION 14818 CLUBHOUSE DR, HELENDALE, CA 92342	INSPECTOR Melissa Nano

Total # of Images: 0