



Public Health
Environmental Health Services




www.SBCounty.gov

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME SUNSET VILLAGE CONDOS		DATE 6/10/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 6/30/2015
LOCATION 16770 SAN BERNARDINO AV, FONTANA, CA 92335			INSPECTOR Patrick Baccari	
MAILING ADDRESS PO BOX 3589, MISSION VIEJO CA 92690			IDENTIFIER: Spa North11	
<input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input checked="" type="checkbox"/> ACCOUNT			SERVICE: 008 - INSPECTION - ATTEMPTED	
TIME IN 3:00 PM	TIME OUT 3:32 PM	FACILITY ID FA0008614	RELATED ID PR0014389	PE 3623
			RESULT: 00 - NOT APPLICABLE	
			ACTION: 00 - NOT APPLICABLE	

RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	40
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K506 Water Quality - Critical – Water pH 7.2 to 7.8 ⚠ CRITICAL ⚠

POINTS 5	Compliance Date: Not Specified	Inspector Comments: Ph is too high. Adjust Ph to an acceptable level. Chlorine is not effective sanitizer at a high Ph.
	Not In Compliance	
	Violation Reference - HSC - 65530	

Violation Description: The pool operator shall maintain public pool water at pH 7.2 to 7.8.

36K549 Equipment - Spa Pool Aeration System

POINTS NA	Compliance Date: Not Specified	Inspector Comments: Repair air jets to spa.
	Not In Compliance	
	Violation Reference - CCR 24 - 3138B.1	

Violation Description: A spa pool aeration and/or jet system shall be completely separate from the recirculation system and shall not be interconnected with any other pool.

Overall Inspection Comments

Pool and spa's must comply with plan check requirements and receive a final inspection prior to opening for use.

Signature(s) of Acknowledgement

NAME: Steven Rich
TITLE:

Total # of Images: 0