



Public Health
Environmental Health Services



www.SBCounty.gov

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

| | | | | |
|--|----------------------------|---------------------------------|---|-------------------|
| FACILITY NAME EUREKA MANOR | | DATE 7/2/2015 | REINSPECTION DATE Not Specified | PERMIT EXPIRATION |
| LOCATION 1525 E EUREKA ST, SAN BERNARDINO, CA 92404 | | | INSPECTOR Anies Kondoker | |
| MAILING ADDRESS 1525 E EUREKA ST, SAN BERNARDINO, CA 92404 | | | IDENTIFIER: None | |
| TIME IN 4:53 PM | TIME OUT 5:02 PM | FACILITY ID FA0008381 | RELATED ID CO0051432 | PE 3620 |
| | | | SERVICE: 004 - COMPLAINT - INITIAL RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE ACTION: 01 - NO FURTHER ACTION REQUIRED | |

RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility

| |
|-------------------|
| Ideal |
| In Compliance |
| Not in Compliance |



| | |
|---------------------|---------|
| temperature (°F) | No Data |
| observed flow (gpm) | No Data |
| required flow (gpm) | No Data |
| volume (gal) | No Data |
| area (sq ft) | No Data |
| occupancy | No Data |

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K999 Complaint Inspection

| | | |
|---------------------|--------------------------------|---------------------|
| POINTS NA | Compliance Date: Not Specified | Inspector Comments: |
| | Not In Compliance | |
| | Violation Reference - HSC | |

Description: A complaint report has been received by Environmental Health.

Overall Inspection Comments

The pool and spa water is no longer green.
No access to the pool enclosure. Manager is not on site at this time.
Bottom of the pool was not visible from outside pool enclosure.
Observed good spa water clarity.
No access to equipment room. Sound of pump motor could be heard from outside.
A resident stated that a pool service person has not come to service the pool yet.

Call health dept prior opening.

Signature(s) of Acknowledgement

NAME:
TITLE:
Total # of Images: 0