



RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME KENDALL PALMS APARTMENTS				REINSPECTION DATE Not Specified	INSPECTOR Yvette Velasco	DATE 10/21/2015
LOCATION 3943 N H ST, SAN BERNARDINO, CA 92404				PERMIT EXPIRATION 8/31/2016	IDENTIFIER: Pool SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION	
TIME IN 9:39 AM	TIME OUT 10:01 AM	FACILITY ID FA0008920	RELATED ID PR0013853	PE 3620	RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE ACTION: 15 - PERMIT REINSTATED / FACILITY RE-OPEN	

RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:
1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump
Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K992 Permit Reinstatement

POINTS
NA

Compliance Date: Not Specified
Not In Compliance
Violation Reference - HSC

Inspector Comments: During the last routine inspection the free chlorine was observed high, the light fixture was observed lose, the light was observed non-functional, and the GFCI was observed non-functional.

Observed the free chlorine levels in the pool at 7.6ppm and the light fixture intact. Observed the light non-functional and the GFCI for the light not yet repaired due to the light not yet repaired. Observed sign stating "no use of pool after dark" at the front gate door.

Ensure to repair the light fixture inside of the pool as well as the GFCI. Inspector will follow up on the GFCI and light fixture during the next routine inspection.

Description: The health permit to operate is hereby reinstated and facility may open.

Overall Inspection Comments

No summary comments have been made for this inspection.

Signature(s) of Acknowledgement

NAME: Shila Valdez
TITLE:

Total # of Images: 0