



RETAIL FOOD PROTECTION - OFFICIAL INSPECTION REPORT

FACILITY NAME BOBA TEA HOUSE			REINSPECTION DATE Not Specified	INSPECTOR Robert Adams	DATE 9/30/2015
LOCATION 25696 BARTON RD, LOMA LINDA, CA 92354			PERMIT EXPIRATION	IDENTIFIER: None	
TIME IN 3:55 PM	TIME OUT 4:43 PM	FACILITY ID FA0010268	RELATED ID CO0052350	PE 1620	SERVICE: 004 - COMPLAINT - INITIAL RESULT: 05 - CORRECTIVE ACTION / FOLLOW UP REQU ACTION: 03 - REINSPECTION REQUIRED

RETAIL FOOD PROTECTION - Public Eating PI (0-24 Seats)

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

16K999 Complaint Inspection

Compliance Date: Not Specified
Not In Compliance
Reference - HSC

Inspector Comments: Complaint was received regarding the installation of a new hood and cooking equipment in this facility. Made contact with the owner which stated that a new fan unit was installed a year ago and a char broiler was added in place of a wok. Informed owner that EHS approval is required prior to making changes to any food facility. Observed kitchen extremely hot. Observed custom hood. See report for corrective action.

Ensure hood is ventilating correctly per mechanical code.

Description: A complaint report has been received by Environmental Health.

17K371 Ventilation - Mechanical Exhaust - Test

Compliance Date: Not Specified
Not In Compliance
Reference - CCDEH Guidelines - CCDEH

Inspector Comments: Provide a certified air balance test for the hood installed at this facility. Provide report to robert.adams@dph.sbcounty.gov by Oct 13, 2015. Scheduled charged follow up on Oct 14, 2015 if the air balance report is not received.

Description: Mechanical exhaust system requires an Air-Balance test by a licensed or certified technician.

Overall Inspection Comments

No summary comments have been made for this inspection.

Signature(s) of Acknowledgement

NAME:
TITLE:

Total # of Images: 0