



**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME <b>VALENCIA WOODS APARTMENTS</b>				REINSPECTION DATE <b>Not Specified</b>	INSPECTOR <b>Isaac Gebreslassie</b>	DATE <b>9/24/2015</b>
LOCATION <b>16311 VALENCIA AV, FONTANA, CA 92335</b>				PERMIT EXPIRATION <b>5/31/2016</b>	IDENTIFIER: Pool	
TIME IN <b>10:40 AM</b>	TIME OUT <b>11:34 AM</b>	FACILITY ID <b>FA0008610</b>	RELATED ID <b>PR0016997</b>	PE <b>3620</b>	SERVICE: 112 - INVESTIGATION - LICENSE / PERMIT	
				RESULT: 05 - CORRECTIVE ACTION / FOLLOW UP REQU		
				ACTION: 03 - REINSPECTION REQUIRED		

**RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility**

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	55
volume (gal)	19,950
area (sq ft)	665
occupancy	33

**IMPORTANT: Replacement of Suction Outlet Covers**  
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:  
1. Meet the latest ANSI/APSP-16 performance standard  
2. Be rated for the maximum designed flow-rate of the pump  
Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

**36K990 Survey Inspection**

**POINTS**  
**NA**

Compliance Date: Not Specified  
Not In Compliance  
Violation Reference - SBCC - SBC Policy

**Inspector Comments:** A survey inspection was conducted on this date to verify whether pool still remains closed as a result of AB 1020 anti entrapment law non-compliance observed at the time of routine inspection. As a result today observed that the anti entrapment vacuum release system (Stingl) installed. However, this system was not approved by our office. Operator is required to submit the AB1020 compliance form signed by a qualified engineer. Until such time pool remains closed for public use.

**Description:** A survey inspection was conducted on this date.

**Overall Inspection Comments**

No summary comments have been made for this inspection.

**Signature(s) of Acknowledgement**

NAME: Marcus  
TITLE: maintenance

Total # of Images: 0