



Public Health
Environmental Health Services

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME LINCOLN ELEMENTARY SCHOOL		DATE 8/21/2015	REINSPECTION DATE Next Routine	PERMIT EXPIRATION
LOCATION 440 N ALLYN ST, ONTARIO, CA 91764			INSPECTOR John Ramos	
MAILING ADDRESS 950 W D ST, ONTARIO CA 91762			IDENTIFIER: Pool	
<input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input checked="" type="checkbox"/> ACCOUNT			SERVICE: 001 - INSPECTION - ROUTINE	
TIME IN 10:40 AM	TIME OUT 11:23 AM	FACILITY ID FA0002540	RELATED ID PR0016970	PE 3603
			RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED	
			ACTION: 01 - NO FURTHER ACTION REQUIRED	

RECREATIONAL HEALTH - Public School Pool / Spa

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$4.08 per 1 minute with a minimum time of 30 minutes, and a minimum charge of \$122.50.




100

SCORE

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	94.0
observed flow (gpm)	100
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

IMPORTANT: Replacement of Suction Outlet Covers
 Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

- Meet the latest ANSI/APSP-16 performance standard
- Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

No Violations Cited

Overall Inspection Comments

No violations were observed. Pool has recently been filled and has been superchlorinated prior to opening for use.

If you have any questions contact John Ramos at (800) 442-2283 or at John.Ramos@dph.sbcounty.gov

Signature(s) of Acknowledgement

Manish Kumar Rajas

NAME:
TITLE:

Total # of Images: 0