



RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME VICTORIA PLACE HOA		REINSPECTION DATE Not Specified		INSPECTOR Mark Williams	DATE 8/26/2016
LOCATION 9733 WOODLEAF, RANCHO CUCAMONGA, CA 91730				PERMIT EXPIRATION 12/31/2016	IDENTIFIER: Pool
TIME IN 11:35 AM	TIME OUT 11:48 AM	FACILITY ID FA0006818	RELATED ID PR0014782	PE 3620	SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION
					RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED
					ACTION: 01 - NO FURTHER ACTION REQUIRED



RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	85
volume (gal)	30,780
area (sq ft)	912
occupancy	45

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K994 Reinspection

POINTS NA	Compliance Date: Not Specified	Inspector Comments: On this date the pool operator requested a re inspection due to the pool closure on 8-24-2016. The health permit for this pool was suspended on 8-24-2016 due the main gate not self latching. On this date the main gate was observed to self close latch. The permit to operate this pool was reinstated this date. This pool was closed at the time of this inspection. This pool may now reopen.
	Not In Compliance	
	Violation Reference - HSC	

Description: Reinspection conducted at this time to determine compliance from prior inspection.

36K528 Safety – Safety equipment

POINTS 1	Compliance Date: Not Specified	Inspector Comments: The rope to the life ring was missing. Provide an approved rope to the life ring at least 3/16 inch in diameter and long enough to span the widest part of the pool.
	Not In Compliance	
	Violation Reference - HSC - 65540	

Violation Description: Except for spray grounds without standing water, the pool operator shall ensure that the following safety and first aid equipment is provided and maintained readily visible and available for use at the public pool at all times:

- (1) A 17-inch-minimum (exterior diameter) life ring with an attached throw rope with a minimum 3/16-inch diameter. The throw rope shall be of sufficient length to span the maximum width of the public pool and shall be stored in such a way as to prevent kinking or fouling.
- (2) A 12-foot-minimum fixed-length rescue pole with a permanently attached body hook. For spas, the length of the rescue pole shall be of sufficient length to effectuate rescue.

For public pools that exceed 75 feet in length or 50 feet in width, the pool operator shall provide a rescue pole and a life ring on at least two opposing sides of the public pool at centralized locations.

For public pools with lifeguard personnel on duty, the pool operator of each public pool area shall have the following additional safety equipment:

- (1) A Red Cross 10-Person Industrial First Aid Kit or the equivalent.
- (2) An operating telephone.
- (3) A backboard and head immobilizer.

Overall Inspection Comments

This re-inspection was conducted at the request of the operator.
This pool was reopened this date and the permit to operate this pool was reinstated.
All available gates at this pool were observed to self close and self latch.

Signature(s) of Acknowledgement



Public Health
Environmental Health Services

www.SBCounty.gov
www.SBCounty.gov/dph/dehs

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME VICTORIA PLACE HOA	DATE 8/26/2016
LOCATION 9733 WOODLEAF , RANCHO CUCAMONGA, CA 91730	INSPECTOR Mark Williams

NAME: duane glenn koch
TITLE: pool tech

Total # of Images: 0