



RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME BALDY VIEW SPRINGS APARTMENTS				REINSPECTION DATE Not Specified	INSPECTOR Eduardo Ramirez	DATE 9/27/2016
LOCATION 853 ORCHID CT, UPLAND, CA 91786				PERMIT EXPIRATION 8/31/2017	IDENTIFIER: Pool	
TIME IN 9:50 AM	TIME OUT 10:15 AM	FACILITY ID FA0008573	RELATED ID PR0014599	PE 3620	SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE ACTION: 15 - PERMIT REINSTATED / FACILITY RE-OPEN	


RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	48
volume (gal)	17,167
area (sq ft)	510
occupancy	26

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:
 1. Meet the latest ANSI/APSP-16 performance standard
 2. Be rated for the maximum designed flow-rate of the pump
 Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K992 Permit Reinstatement

POINTS
NA

Compliance Date: Not Specified
Not In Compliance
Violation Reference - HSC

Inspector Comments: This re inspection was conducted on this date upon the request of the operator. Pool was closed and the health permit was suspended on 09/13/2016 due to pool gate not able to self-close/ self latch and iron fence missing some legs on the enclosure. Upon the re inspection conducted on this date, the gate was found to self-close/ self-latch ad the enclosure gap was welded correctly. The health permit to operate this pool was reinstated this date. Pool shall now open.

Description: The health permit to operate is hereby reinstated and facility may open.

Overall Inspection Comments

No summary comments have been made for this inspection.

Signature(s) of Acknowledgement

SNA

NAME:
TITLE:

Total # of Images: 0