



RETAIL FOOD PROTECTION - OFFICIAL INSPECTION REPORT

FACILITY NAME HIGHLAND CHEVRON		REINSPECTION DATE 10/21/2015		INSPECTOR Sierra Clayborn		DATE 10/7/2015	
LOCATION 2505 E HIGHLAND AV, SAN BERNARDINO, CA 92346				PERMIT EXPIRATION 8/31/2015		IDENTIFIER: Store	
TIME IN 3:20 PM	TIME OUT 3:47 PM	FACILITY ID FA0000989	RELATED ID PR0013386	PE 1611	SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION RESULT: 05 - CORRECTIVE ACTION / FOLLOW UP REQU ACTION: 03 - REINSPECTION REQUIRED		

RETAIL FOOD PROTECTION - Food Handling PI (500-2499 SqFt)

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

16K994 Reinspection

Compliance Date: Not Specified

Not In Compliance

Reference - HSC

Inspector Comments: During re-score inspection at adjacent facility inside of the same building as this food facility, observed inadequate wastewater disposal due to a broken/cracked wastewater drainage pipe beneath concrete outside of food facility.

This food facility is currently prohibited from selling and serving non-prepackaged food until adequate wastewater disposal can be obtained. Non-prepackaged food includes nacho cheese, chili, soda fountain drinks and coffee.

Description: Reinspection conducted at this time to determine compliance from prior inspection.

16K022 Sewage and wastewater properly disposed

Compliance Date: Not Specified

Not In Compliance

Violation Reference - HSC - 114197

Inspector Comments: Observed a plumbing repair company on site at the start of the inspection. Observed standing waste water in both floor sinks, at about 90% capacity, in ware washing and food prep areas. Manager (of adjacent Subway) stated that waste water had backed up onto the floor earlier that week. Manager stated that this was the 3rd visit by the plumbing company in the last 1.5 weeks. Plumber on site stated that during the last visit, a crack was discovered in the waste water drain line and part of the crack was repaired, but the part beneath the concrete next to the building was not. Currently, the blockage in the line is caused by an excess of toilet paper. Plumber cleared the line during the inspection, but stated that issue was reoccur within 2 days if the toilets were used.

Facility must be able to provide adequate wastewater disposal.
Due to lack of adequate waste water disposal, the sale and preparation of non-prepackaged food is prohibited.

Repair/replace appropriate plumbing lines to regain adequate wastewater disposal at food facility. Provide bill of repair to inspector at time of reopening.

Violation Description: All liquid waste must drain to an approved fully functioning sewage disposal system. (114197) Toilet facilities must be operable.

Overall Inspection Comments

Facility must be able to provide adequate wastewater disposal.

Due to lack of adequate waste water disposal, the sale and preparation of non-prepackaged food is prohibited.

Repair/replace appropriate plumbing lines to regain adequate wastewater disposal at food facility. Provide bill of repair to inspector at time of reopening of adjacent Subway facility.

Signature(s) of Acknowledgement

NAME: Richi Sorn
TITLE: Person in Charge

Total # of Images: 0