



RECREATIONAL HEALTH PLAN CHECK - OFFICIAL PLAN REVIEW REPORT

FACILITY NAME 9743 WOO		REINSPECTION DATE Not Specified		INSPECTOR Aleasha Reed	DATE 2/11/2016
LOCATION 9743 WOODLEAF, RANCHO CUCAMONGA, CA 91730				PERMIT EXPIRATION	IDENTIFIER: None
TIME IN 11:30 AM	TIME OUT 12:30 PM	FACILITY ID FA0006818	RELATED ID SR0071073	PE 3711	SERVICE: 126 - PLAN CHECK FIELD INSPECTION RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE ACTION: 01 - NO FURTHER ACTION REQUIRED

RECREATIONAL HEALTH PLAN CHECK - Plnck Pool Major Remodel 0-999 SqFt

IMPORTANT: Replacement of Suction Outlet Covers

Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

37K064 Enclosure - General - 4"

Compliance Date: Not Specified

Not In Compliance

Reference - CCR 24 - 3118B(a)

Inspector Comments: Observed several areas where opening under fence exceeded 4 inches. Ensure bottom of fence has less than a 4 inch clearance. Recommend welding an additional horizontal bar to bottom of existing fence.

Description: Openings, holes or gaps in the enclosure, doors and/or gates shall not allow the passage of a four (4) inch diameter sphere.

37K278 Structure - Stairs

Compliance Date: Not Specified

Not In Compliance

Reference - CCR 24 - 3110B.3

Inspector Comments: Observed riser not uniform with top step exceeding 12 inches. Ensure risers and trend are uniform. See text below.

Description: Each step of a stair must have the same dimensions, with a tread of not less than 12 inches, except for a curved top step which must be 18 inches in width at the widest point. Risers must be uniform and must not exceed 12 inches in height.

37K510 Plans - Preliminary Inspection

Compliance Date: Not Specified

Not In Compliance

Reference - Reference Number - SBC Policy

Inspector Comments: Preliminary inspection conducted today for the remodel of an existing pool and spa. Scope of remodel includes: replaster of spa, new skimmers on both pool and spa, new deck, new hand rails for both pool and spa, additional fencing, and new valves at recirculation equipment.

Do not fill pool and spa with water until gap at bottom of fencing has been reduced.

Call 1-800-442-2283 to schedule a final inspection when all construction has been completed, pool and spa are filled with water, and all equipment is operational.

All chemicals should be balanced for final inspection.

Description: Preliminary inspection

Overall Inspection Comments

Continue with construction as per approved plans.

Note: No diving markers are not required on spas.

Signature(s) of Acknowledgement

NAME:

TITLE:

Total # of Images: 0