



Public Health
Environmental Health Services

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

| | | | | |
|---|---------------------|--------------------------|--|--------------------------------|
| FACILITY NAME ASCOT PARK APARTMENTS CALIFORNIA | | DATE 5/7/2015 | REINSPECTION DATE Not Specified | PERMIT EXPIRATION 6/30/2015 |
| LOCATION 1422 E 9TH ST, SAN BERNARDINO, CA 92410 | | | INSPECTOR Chris Nwadike | |
| MAILING ADDRESS 1422 E 9TH ST, SAN BERNARDINO CA 92410 | | | IDENTIFIER: Pool | |
| | | | SERVICE: 001 - INSPECTION - ROUTINE | |
| TIME IN 1:36 PM | TIME OUT 2:44 PM | FACILITY ID FA0006560 | RELATED ID PR0014083 | PE 3620 |
| | | | RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE | |
| | | | ACTION: 01 - NO FURTHER ACTION REQUIRED | |




RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

91
SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

| |
|-------------------|
| Ideal |
| In Compliance |
| Not in Compliance |



| | |
|---------------------|---------|
| temperature (°F) | 72.0 |
| observed flow (gpm) | 0 |
| required flow (gpm) | No Data |
| volume (gal) | No Data |
| area (sq ft) | No Data |
| occupancy | 25 |

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:
1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump
Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K570 Maintenance – Critical – Flow rate/Turnover rate ⚠ CRITICAL ⚠

| | | |
|---------------------------|--|--|
| POINTS 5 | Compliance Date: Not Specified | Inspector Comments: Observed stuck flow meter. |
| | Not In Compliance | Repair or replace. |
| | Violation Reference - CCR - 3124B, 65525 | |

Violation Description: The recirculation system shall have the capacity to provide a complete turnover of pool water in:

1. One-half hour or less for a spa pool; and
2. One-half hour or less for a spray ground; and
3. One hour or less for a wading pool; and
4. Two hours or less for a medical pool; and
5. Six hours or less for all other types of public pools.

The variation in flow rate of an operating recirculation system shall be such as not to reduce the flow below 75 percent of the rate required in section 3124B, Title 24, California Code of Regulations.

36K518 Water Quality – Cyanuric acid concentration

| | | |
|---------------------------|-----------------------------------|--|
| POINTS 1 | Compliance Date: Not Specified | Inspector Comments: Observed cyanuric acid level at 109.00ppm. |
| | Not In Compliance | Maintain below 100.00ppm (under 50.0ppm preferred). |
| | Violation Reference - HSC - 65530 | |

Violation Description: The maximum concentration of cyanuric acid in public pool water shall not exceed 100.0 ppm.

36K556 Equipment – Plumbing labeled

| | | |
|---------------------------|--------------------------------------|---|
| POINTS 1 | Compliance Date: Not Specified | Inspector Comments: Observed no labels/markings on the piping in the equipment/pump area showing the direction of water flow/recirculation. |
| | Not In Compliance | The direction of water flow for the recirculation equipment shall be labeled clearly with directional symbols such as arrows on all piping in the equipment area. |
| | Violation Reference - CCR 24 - 3120B | |

Violation Description: The direction of flow for the recirculation equipment shall be labeled clearly with directional symbols such as arrows on all piping in the equipment area. Where the recirculation equipment for more than one pool is located on site, the equipment shall be marked as to which pool the system serves. Valves and plumbing lines shall be labeled clearly with the source or destination descriptions.



Public Health

Environmental Health Services

www.SBCounty.gov

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

| | |
|---|----------------------------|
| FACILITY NAME ASCOT PARK APARTMENTS CALIFORNIA | DATE 5/7/2015 |
| LOCATION 1422 E 9TH ST, SAN BERNARDINO, CA 92410 | INSPECTOR Chris Nwadike |

IMPORTANT: Replacement of Suction Outlet Covers

Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K562 Skimmers – Pool skimming systems

| | | |
|---------------------------|-----------------------------------|---|
| POINTS 1 | Compliance Date: Not Specified | Inspector Comments: Observed no weir gates to the skimmers. Provide the weir gates. |
| | Not In Compliance | |
| | Violation Reference - CCR - 3136B | |

Violation Description: The pool shall be equipped with one or more skimming methods to provide continuous skimming of the pool water and shall be capable of continually withdrawing not less than 100 percent of the flow rate. Each surface skimmer shall comply with the requirements in accordance with section 3136B, Title 24, California Code of Regulations.

36K582 Maintenance - Public pool site maintenance

| | | |
|---------------------------|-----------------------------------|---|
| POINTS 1 | Compliance Date: Not Specified | Inspector Comments: Observed cracks along the pool deck and more pronounced by the skimmers. Provide repairs. |
| | Not In Compliance | |
| | Violation Reference - HSC - 65535 | |

Violation Description: The pool operator shall keep all parts of the public pool site well-maintained, including, but not limited to, the public pools, water treatment systems, ancillary facilities, signs, showers, toilets, dressing facilities, drinking fountains, diaper-changing stations, floors, walls, partitions, doors, and lockers.

Overall Inspection Comments

No summary comments have been made for this inspection.

Signature(s) of Acknowledgement

NAME:
TITLE:

Total # of Images: 0