



Public Health

Environmental Health Services

www.SBCounty.gov

RECREATIONAL HEALTH PLAN CHECK - OFFICIAL PLAN REVIEW REP

FACILITY NAME PARK VISTA		DATE 6/30/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION
LOCATION 1031 S PALMETTO AV, ONTARIO, CA 91762			INSPECTOR Bennetta Betbadal	
MAILING ADDRESS 675 W FOOTHILL BL CLAREMONT, CA 91711			IDENTIFIER: None	
TIME IN 3:55 PM			SERVICE: 025 - PLAN REVIEW	
TIME OUT 4:16 PM			RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED	
FACILITY ID FA0008422			ACTION: 55 - PLANS APPROVED	
RELATED ID SR0068930			PE 3716	

RECREATIONAL HEALTH PLAN CHECK - Plnck Pool Minor Remodel - all

IMPORTANT: Replacement of Suction Outlet Covers

Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

37K980 Plans - Plan Review Approved

Compliance Date: Not Specified

Not In Compliance

Reference - HSC

Inspector Comments: Plan is approved for replaster of pool and spa. Replace hand rails, new trim tiles, waterline tiles, replace drain covers.

Description: Plans have been approved and this correction sheet is a part of the approved plans.

37K272 Structure - Spa

Compliance Date: Not Specified

Not In Compliance

Reference - Reference Number - SBC Policy

Inspector Comments: Per new pool code, spa has to have to handrails.

Description: In existing spas, two (2) safety handrails must be provided when the bench is not flush with one (1) of the step treads. One (1) handrail shall be installed at each side of the steps where the step drops off to the bench.

37K456 Equipment - Plumbing – Drains

Compliance Date: Not Specified

Not In Compliance

Reference - Reference Number - 116064.1

Inspector Comments: Strongly recommend to split the main drain for the pool.

Strongly recommend to split the main pump line for the spa.

Ensure to leave the split and "T" exposed for verification during replaster inspection.

Description: A pool shall have at least two main drains per pump that are hydraulically balanced and symmetrically plumbed [evenly-split] through one or more "T" fittings, and that are separated by a distance of at least three feet [edge to edge] in any dimension between the drains.

Overall Inspection Comments

Pool pump: Pentair WEF 2 HP
Pool Filter: Purex 72 sq ft
Suction line: 2"
Return line" 2"

Spa Pump: 1 HP
Spa filter: Purez 48 sq ft
Suction line: 2"
Return line: 2"

Provide depth markers and no diving tiles on the decks.

Signature(s) of Acknowledgement



Public Health
Environmental Health Services

RECREATIONAL HEALTH PLAN CHECK - OFFICIAL PLAN REVIEW REP

FACILITY NAME PARK VISTA	DATE 6/30/2015
LOCATION 1031 S PALMETTO AV, ONTARIO, CA 91762	INSPECTOR Bennetta Betbadal

NAME:
TITLE:

Total # of Images: 0