



RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME BONANZA MOBILE ESTATES				REINSPECTION DATE Not Specified	INSPECTOR Yvette Velasco	DATE 9/28/2015
LOCATION 13645 5TH ST B, YUCAIPA, CA 92399				PERMIT EXPIRATION 12/31/2015	IDENTIFIER: Pool SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION	
TIME IN 10:39 AM	TIME OUT 10:46 AM	FACILITY ID FA0007228	RELATED ID PR0014976	PE 3620	RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED ACTION: 01 - NO FURTHER ACTION REQUIRED	




RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:
1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump
Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K994 Reinspection

POINTS
NA

Compliance Date: Not Specified
Not In Compliance
Violation Reference - HSC

Inspector Comments: During the last inspection one gate door was observed not self-latching.

Observed door locked and alternate door being used. Person in charge stated that gate will remain locked and repaired prior to opening the pool area for pool season next year.

Ensure to maintain gate door locked and use alternate gate door. No additional inspections are necessary at this time.

Description: Reinspection conducted at this time to determine compliance from prior inspection.

Overall Inspection Comments

No summary comments have been made for this inspection.

Signature(s) of Acknowledgement

NAME:
TITLE:

Total # of Images: 0