



**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME <b>LOS RANCHOS</b>				REINSPECTION <b>Not Specified</b>	INSPECTOR <b>Kelly Eredia</b>	DATE <b>8/18/2016</b>
LOCATION <b>20843 WAALEW RD, APPLE VALLEY, CA 92307</b>				PERMIT <b>2/28/2017</b>	IDENTIFIER: East Spa	
TIME IN <b>9:35 AM</b>	TIME OUT <b>10:07 AM</b>	FACILITY ID <b>FA0004537</b>	RELATED ID <b>PR0016316</b>	PE <b>3623</b>	SERVICE: 001 - INSPECTION - ROUTINE	
					RESULT: 05 - CORRECTIVE ACTION / FOLLOW UP REQUIRED	
					ACTION: 13 - PERMIT SUSPENDED / FACILITY CLOSED	

**RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility**



Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

**93**

SCORE

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

<b>Ideal</b>
<b>In Compliance</b>
<b>Not in Compliance</b>



temperature (°F)	No Data
observed flow (gpm)	101
required flow (gpm)	65
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

**IMPORTANT: Replacement of Suction Outlet Covers**  
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

- Meet the latest ANSI/APSP-16 performance standard
- Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your

**36K995 Permit - Suspension** **⚠ CRITICAL ⚠**

<b>POINTS</b> <b>NA</b>	Compliance Date: <b>Not Specified</b> Not In Compliance Violation Reference - HSC	Inspector Comments: Permit is suspended due to high chlorine level.
----------------------------	---	---

**Violation Description:** Violation(s) observed pose an immediate threat to public health and safety. The health permit to operate is hereby suspended and the pool/spa ordered closed until the listed violation(s) have been corrected and verified by Environmental Health Services (EHS). The facility is to remain closed until permission from EHS is given. Contact your inspector at your local office to schedule a reinspection to reinstate the health permit. The facility is posted closed; do not move, hide, or remove the sign. Reopening of the pool/spa without the approval by EHS, may result in an hourly billable Professional Services fee.

**36K506 Water Quality - Critical – Water pH 7.2 to 7.8** **⚠ CRITICAL ⚠**

<b>POINTS</b> <b>5</b>	Compliance Date: <b>Not Specified</b> Not In Compliance Violation Reference - HSC - 65530	Inspector Comments: Observed pH level high above 8.0. Maintain pH level from 7.2 to 7.8.
---------------------------	---	--

**Violation Description:** The pool operator shall maintain public pool water at pH 7.2 to 7.8.

**36K526 Safety - Emergency shut-off switch**

<b>POINTS</b> <b>1</b>	Compliance Date: <b>Not Specified</b> Not In Compliance Violation Reference - CCR 24 - 3138B.5	Inspector Comments: Observed screw placed in emergency shut-off switch preventing the switch from being used. I removed the screw, and tested the switch. It is functional. Ensure there is no obstruction of the switch as it is easily accessible to use at all times in case of emergency.
---------------------------	--	---

**Violation Description:** A clearly labeled emergency shut off switch for the control of both the recirculation system and the aeration and/or jet system shall be installed adjacent to the spa pool.



**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME <b>LOS RANCHOS</b>	DATE <b>8/18/2016</b>
LOCATION <b>20843 WAALEW RD, APPLE VALLEY, CA 92307</b>	INSPECTOR <b>Kelly Eredia</b>

**36K562 Skimmers - Pool skimming systems**

<b>POINTS</b> <b>1</b>	<b>Compliance Date: Not Specified</b>	<b>Inspector Comments:</b> Observed float assembly missing from skimmer. Ensure all skimmer components are present and properly functional to allow proper skimming.
	<b>Not In Compliance</b>	
	<b>Violation Reference - CCR - 3136B</b>	

**Violation Description:** The pool shall be equipped with one or more skimming methods to provide continuous skimming of the pool water and shall be capable of continually withdrawing not less than 100 percent of the flow rate. Each surface skimmer shall comply with the requirements in accordance with section 3136B, Title 24, California Code of Regulations.

**Overall Inspection Comments**

I was not able to access the pool recirculation equipment.

Permit is suspended due to high chlorine level. Contact the department of Environmental Health at 800-442-2283 to schedule a reinspection.

**Signature(s) of Acknowledgement**

NAME: SNA  
TITLE:

Total # of Images: 0