



Public Health
Environmental Health Services

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

| | | | | |
|---|--|--|------------------------------------|--------------------------------|
| FACILITY NAME MONTESSORI SCHOOL OF CHINO HILLS | | DATE 6/22/2015 | REINSPECTION DATE Not Specified | PERMIT EXPIRATION 7/31/2015 |
| LOCATION 14635 PIPELINE AV, CHINO, CA 91710 | | INSPECTOR Casey Salazar | | |
| MAILING ADDRESS 2333 VELLANO CLUB DR, CHINO HILLS CA 91709 | | IDENTIFIER: Pool | | |
| TIME IN 12:45 PM | | SERVICE: 001 - INSPECTION - ROUTINE | | |
| TIME OUT 1:43 PM | | RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE | | |
| FACILITY ID FA0004795 | | ACTION: 01 - NO FURTHER ACTION REQUIRED | | |
| RELATED ID PR0015229 | | PE 3620 | | |




RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

97
SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$ 4.08 per 1 minute with a minimum time of 30 minutes, and a minimum charge of \$122.50.

| |
|-------------------|
| Ideal |
| In Compliance |
| Not in Compliance |



| | |
|---------------------|-------|
| temperature (°F) | 90.4 |
| observed flow (gpm) | 65 |
| required flow (gpm) | 24 |
| volume (gal) | 8,796 |
| area (sq ft) | 382 |
| occupancy | 14 |

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:
1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump
Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K556 Equipment – Plumbing labeled

| | | |
|---------------------------|--------------------------------------|--|
| POINTS 1 | Compliance Date: Not Specified | Inspector Comments: Observed directional arrows missing from pool recirculation equipment. Label to indicate direction of flow. |
| | Not In Compliance | |
| | Violation Reference - CCR 24 - 3120B | |

Violation Description: The direction of flow for the recirculation equipment shall be labeled clearly with directional symbols such as arrows on all piping in the equipment area. Where the recirculation equipment for more than one pool is located on site, the equipment shall be marked as to which pool the system serves. Valves and plumbing lines shall be labeled clearly with the source or destination descriptions.

36K562 Skimmers - Pool skimming systems

| | | |
|---------------------------|-----------------------------------|--|
| POINTS 1 | Compliance Date: Not Specified | Inspector Comments: Observed float assembly missing from skimmer. Provide required skimmer equipment. |
| | Not In Compliance | |
| | Violation Reference - CCR - 3136B | |

Violation Description: The pool shall be equipped with one or more skimming methods to provide continuous skimming of the pool water and shall be capable of continually withdrawing not less than 100 percent of the flow rate. Each surface skimmer shall comply with the requirements in accordance with section 3136B, Title 24, California Code of Regulations.

36K582 Maintenance - Public pool site maintenance

| | | |
|---------------------------|-----------------------------------|---|
| POINTS 1 | Compliance Date: Not Specified | Inspector Comments: Observed pool shell chipping. Repair pool shell with a smooth waterproof interior finish that will withstand repeated brushing, scrubbing and cleaning procedures. Observed P rails loose. Tighten hand rails. Observed pool light not working. Repair/replace pool light and ensure GFCI is operating properly. Observed water pooled in pump room. Drain appears to be clogged. Clean drain and remove standing water. Observed no paper towels in dispenser of women's restroom. Provide paper towels in dispenser. |
| | Not In Compliance | |
| | Violation Reference - HSC - 65535 | |

Violation Description: The pool operator shall keep all parts of the public pool site well-maintained, including, but not limited to, the public pools, water treatment systems, ancillary facilities, signs, showers, toilets, dressing facilities, drinking fountains, diaper-changing stations, floors, walls, partitions, doors, and lockers.

Overall Inspection Comments

Pool inspection conducted.



Public Health
Environmental Health Services

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

| | |
|---|----------------------------|
| FACILITY NAME MONTESSORI SCHOOL OF CHINO HILLS | DATE 6/22/2015 |
| LOCATION 14635 PIPELINE AV, CHINO, CA 91710 | INSPECTOR Casey Salazar |

Signature(s) of Acknowledgement

NAME:
TITLE: PIC

Total # of Images: 0