



RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME EUREKA MANOR		REINSPECTION DATE Not Specified		INSPECTOR Anies Kondoker	DATE 10/9/2015
LOCATION 1525 E EUREKA ST, SAN BERNARDINO, CA 92404				PERMIT EXPIRATION	IDENTIFIER: None
TIME IN 8:47 AM	TIME OUT 9:17 AM	FACILITY ID FA0008381	RELATED ID CO0052293	PE 3620	SERVICE: 038 - PUBLIC POOL/SPA - RESCORE INSPECTIO RESULT: 05 - CORRECTIVE ACTION / FOLLOW UP REQU ACTION: 13 - PERMIT SUSPENDED / FACILITY CLOSED

RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility



Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

95
SCORE

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

- Meet the latest ANSI/APSP-16 performance standard
- Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K514 Water Quality – Critical – Water clarity **⚠ CRITICAL ⚠**

POINTS 5	Compliance Date: Not Specified	Inspector Comments: Observed pool water to be dark green with floating debris accumulation. Bottom of the pool was not visible from outside fencing area.
	Not In Compliance	
	Violation Reference - HSC - 65527	

Violation Description: The pool operator shall maintain clear pool water while the public pool is in use. The pool operator shall close the public pool if the bottom of the pool at the maximum depth is not clearly visible from the deck. The pool operator shall not reopen the public pool for use until the pool water is clean and clear, and the bottom of the pool at the maximum depth is clearly visible from the deck. If the bottom of the pool is not visible 48 hours following inspection and closure by the enforcing agent, the enforcing agent may order the pool drained.

Overall Inspection Comments

This is a charged inspection.
On an inspection report dated 10/7/2015, the facility was ordered to drain its pool and spa or to bring pool water and spa back into the condition that meets the code.

One of the following options has to be met by Monday, 10/12/2015 at 5 pm:

1. Drain pool and spa water.
2. Bring pool and spa water into compliance that meets the codes.

Failure to comply to meet one of the options above will result in another charged inspection or further legal action.

Signature(s) of Acknowledgement

NAME:
TITLE:



Public Health
Environmental Health Services

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME EUREKA MANOR	DATE 10/9/2015
LOCATION 1525 E EUREKA ST, SAN BERNARDINO, CA 92404	INSPECTOR Anies Kondoker

Total # of Images: 0