



RETAIL FOOD PROTECTION - OFFICIAL INSPECTION REPORT

FACILITY NAME HIGHLAND CHEVRON				REINSPECTION DATE Next Routine	INSPECTOR Sierra Clayborn	DATE 10/9/2015
LOCATION 2505 E HIGHLAND AV, SAN BERNARDINO, CA 92346				PERMIT EXPIRATION 8/31/2015	IDENTIFIER: Store	
TIME IN 8:19 AM	TIME OUT 8:27 AM	FACILITY ID FA0000989	RELATED ID PR0013386	PE 1611	SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED ACTION: 01 - NO FURTHER ACTION REQUIRED	

RETAIL FOOD PROTECTION - Food Handling PI (500-2499 SqFt)

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

16K994 Reinspection

Compliance Date: Not Specified
Not In Compliance
Reference - HSC

Inspector Comments: During re-score inspection at adjacent Subway facility, observed that facility did not have adequate wastewater disposal due to a broken sewer line. Subway facility was closed at that time and this facility was restricted from selling or preparing any non-prepackaged food, though the prepackaged side of the facility was allowed to remain open.

During re-inspection, observed a receipt of repair from Payless 4 Plumbing Inc who had performed the sewer line repair on 10-8-15. Receipt states that the company observed a break in the sewer line during the sewer camera inspection. The concrete in that area was saw cut and the broken line was removed and replaced. Observed all toilets flushing properly and water at 3 compartment sink easily able to drain. No standing water was observed in floor sinks.

Facility has met compliance for proper wastewater disposal requirement at this time and will be allowed to resume open food activities.

Description: Reinspection conducted at this time to determine compliance from prior inspection.

Overall Inspection Comments

No summary comments have been made for this inspection.

Signature(s) of Acknowledgement

NAME: Tony Whitten
TITLE: Manager

Total # of Images: 0