



Public Health
Environmental Health Services




www.SBCounty.gov

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME EUREKA MANOR		DATE 6/30/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION
LOCATION 1525 E EUREKA ST, SAN BERNARDINO, CA 92404			INSPECTOR Anies Kondoker	
MAILING ADDRESS 1525 E EUREKA ST, SAN BERNARDINO, CA 92404			IDENTIFIER: None	
TIME IN 4:26 PM	TIME OUT 4:35 PM	FACILITY ID FA0008381	RELATED ID CO0051393	PE 3620
			SERVICE: 004 - COMPLAINT - INITIAL RESULT: 05 - CORRECTIVE ACTION / FOLLOW UP REQU ACTION: 03 - REINSPECTION REQUIRED	

RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K996 Attempted Inspection

POINTS NA	Compliance Date: Not Specified	Inspector Comments:
	Not In Compliance	
	Violation Reference - HSC	

Description: An inspection was attempted today. Another inspection will be attempted at a later date.

Overall Inspection Comments

A complaint alleged that swimming pool is filthy with green scum.

Findings:

- The pool and spa were closed by inspector on 4/29/15 due to gate/fencing issue and non-operation recirculation system.
- Observed pool and spa closure signs posted by inspector on both gates on 4/29/15 were missing.
- Observed debris accumulation on pool surface and bottom.
- Observed pool water to be green and brown.
- Bottom of the pool was not visible from pool deck.
- Manager stated that the pump is broken.
- Several residents stated that the pool and spa unsanitary condition have been going on for weeks.
- Observed 1 missing vertical bar on east fencing.

Inspector wrap a packaging tape around two bars to provide a temporary barrier.

- No mosquito larvae were observed at this time. However, inspector referred this facility to Vector Control program.

Corrective action:

Facility is given 48 hours to bring the pool and spa water back to be in sanitary condition with functional recirculation system or drain the pool and spa. The missing vertical bar must also be replaced within 48 hours.

Failure to comply will result in a charge re-inspection with a rate of \$245/hr.

Signature(s) of Acknowledgement



Public Health
Environmental Health Services

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME EUREKA MANOR	DATE 6/30/2015
LOCATION 1525 E EUREKA ST, SAN BERNARDINO, CA 92404	INSPECTOR Anies Kondoker

NAME:
TITLE:

Total # of Images: 0