



RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME ARBORGATE APARTMENTS		REINSPECTION DATE Not Specified		INSPECTOR Yanan Zhu	DATE 6/7/2016
LOCATION 16550 ARROW AV, FONTANA, CA 92335				PERMIT EXPIRATION 8/31/2016	IDENTIFIER: Pool
TIME IN 2:20 PM	TIME OUT 2:50 PM	FACILITY ID FA0005172	RELATED ID PR0015141	PE 3620	SERVICE: 001 - INSPECTION - ROUTINE RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE ACTION: 01 - NO FURTHER ACTION REQUIRED

RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility




Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

98
SCORE

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	95
required flow (gpm)	70
volume (gal)	25,194
area (sq ft)	646
occupancy	20

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K558 Equipment – Water supply

POINTS 1	Compliance Date: Not Specified	Inspector Comments: Observed no air gap between wastewater pipe and wastewater drain. Maintain an at least 1 inch air gap between wastewater pipe and wastewater drain to prevent possible back flow water contamination.
	Not In Compliance	
	Violation Reference - CCR - 3127B	

Violation Description: There shall be no direct connection between any potable water supply system and the pool or its piping system unless protected by a backflow prevention device in accordance with Chapter 6 of the California Plumbing Code.

36K562 Skimmers - Pool skimming systems

POINTS 1	Compliance Date: Not Specified	Inspector Comments: Observed one weir gate missing at the skimmer near the shallow end. Provided as described below.
	Not In Compliance	
	Violation Reference - CCR - 3136B	

Violation Description: The pool shall be equipped with one or more skimming methods to provide continuous skimming of the pool water and shall be capable of continually withdrawing not less than 100 percent of the flow rate. Each surface skimmer shall comply with the requirements in accordance with section 3136B, Title 24, California Code of Regulations.

Overall Inspection Comments

No summary comments have been made for this inspection.

Signature(s) of Acknowledgement

NAME: Bianca Soto
TITLE: Manager



Public Health
Environmental Health Services

www.SBCounty.gov
www.SBCounty.gov/dph/dehs

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME ARBORGATE APARTMENTS	DATE 6/7/2016
LOCATION 16550 ARROW AV, FONTANA, CA 92335	INSPECTOR Yanan Zhu

Total # of Images: 0